



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau
Approval expires 12-31-60.
Land Office Santa Fe
Lease No. 57-076958
Unit ✓

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 1 is located 500 ft. from S line and 1050 ft. from E line of sec. 25
24/24, Section 25 (1/4 Sec. and Sec. No.) T-12-N, R-10-W (Twp.) 10-12-W (Range) 10-12-W (Meridian)
Astac Pictured Cliff (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the ground above sea level is 6112 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

T.O. 2015. Perforated from 12/12-70 with 1 shot per foot. Sand-water free with 1170 barrels water and 10,000 lbs. mud. Breakdown Pressure 2000 lbs. Treating 2000 lbs. Final 900 lbs. Injection Rate 11.9 barrels per minute.

Installed 1945' of 1" tubing at 1955'. S I S

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company ATTE OIL & GAS COMPANY

Address P.O. Box 736

Farmington, New Mexico

By Joe C. Salomon
Title Drilling Superintendent

