

STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSION
DISTRICT NO. 3
Phone 99 P. O. Box 697
AZTEC, NEW MEXICO

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 078921-2
Unit SE/4 of 27
designated well with

RECEIVED

EB 2 7 1952

OIL CON. COM.

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 25

19 52

Well No. 1 Federal is located 1650 ft. from S line and 990 ft. from E line of sec. 27

SE/4 SE/4 27
(1/4 Sec. and Sec. No.)

29 N 13 W
(Twp.) (Range)

N. H. P. M.
(Meridian)

Wilcox
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 5706 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

T. D. 1107.
Boiled 5 gal. water per hour. Set retainer at 1107, squeezed with 150 sacks maximum pressure 700 lbs., cleaned casing. Shut in 15 hours with retainer at 1300, break formation with 1200 lbs., back to 100 lbs., mixed 100 sacks, 85 sacks away at 2100 lbs. Finished 1:30 p. m. 2-25-52.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Bay Petroleum Corporation


Address Box 957

Denver, Colorado

By

Pat Lay
Pat Lay

Title District Superintendent



(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office
Lesse No.
Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	
NOTICE OF INTENTION TO CHANGE PLANS	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	
NOTICE OF INTENTION TO SHUT OR ACIDIZE	
NOTICE OF INTENTION TO HULL OR ALTER CASING	
NOTICE OF INTENTION TO ABANDON WELL	
COPIES OF WELLS HISTORY	
SUBSEQUENT REPORT OF ABANDONMENT	
SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
SUBSEQUENT REPORT OF ALTERING CASING	
SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
SUBSEQUENT REPORT OF WATER SHUT-OFF	

(INDICATE ABOVE BY CHECKING IN SPACE FOR REPORT, NOTICE, OR OTHER DATA)

_____ is located _____ ft from _____ line of sec. _____

_____ (Township or Range)
_____ (Section)
_____ (State or Territory)

The elevation of the bench mark above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to productive sands, shales, or other formations, and lengths of proposed casing; indicate including jobs, completion points, and all other important proposed work)

I understand that this plan of work must receive approval in writing from the Geological Survey before operations may be commenced.

Company _____

Address _____

By _____
Title _____