(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	New Mexico
Lease No	03999
Unit	Grambling

NOTICE OF INT	TENTION TO DRILL				
		1 11		OF WATER SHUT-OFF	Į.
NOTICE OF INT	FENTION TO CHANGE PLANS	SUBSE	QUENT REPORT	OF SHOOTING OR ACIDIZING	3
NOTICE OF IN	FENTION TO TEST WATER SHUT-OFF. FENTION TO RE-DRILL OR REPAIR WI	ŧ 11		OF REDRILLING OR REPAIR	1
	TENTION TO RE-DRILL OR REPAIR WI	1 1		OF ABANDONMENT	i
	TENTION TO PULL OR ALTER CASING	l il		L HISTORY	
	TENTION TO ABANDON WELL				l
	(INDICATE ABOVE BY C	HECK MARK NATURE OF	REPORT, NOTICE	, OR OTHER DATA)	
	·	***********	D	ecember 5	, 19
77 11 N.T	9 2.1	6 c c N1:	G	60 (4 from (E) line of	ser 2
/ell No	1 is located 165	Vrt. irom 😁 🗓			sec
N SE NE (½ Sec.	Sec. 28 292 and Sec. No.) (Twp	.) (Range)	N. H	(Meridian)	
Hance		San Juan		Hew Mexico	
	(Field)	(County or Subdivision	n)	(State or Territory)	
	ing pour	nts, and all other import	ant broposed w	ora,	
				•	
Set 7 :	inch casing - 20 lb.	@ 4315' on sh	oulder wi	th 450 sacks.	
	inch casing - 20 lb.			th 450 sacks.	
				th 450 sacks.	
				th 450 sacks.	
				th 450 sacks.	
				th 450 sacks.	
				th 450 sacks.	
Top of		ture Survey is	22801.		commenced
Top of	cement from Temperat	e approval in writing by	22801.		commenced
Top of	coment from Temperat	capproval in writing by	2280° .	Survey before operations may be	
Top of	that this plan of work must receive	e approval in writing by	2280° .		