

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Approval expires 12-31-60
Santa Fe, N. M.

Land Office **181-06093**
Lease No. **A**
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 18, 19**61**

Total **1-A** is located **510** ft. from **{N}** line and **510** ft. from **{E}** line of sec. **30**
NE 1/4 **30** **29N** **13W** **N.M.P.M.**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Total-Callup
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is **7** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

11" hole was drilled to a total depth of 192' and 170' of 2 5/8" 24 lb. casing was cemented at 187" with 125 sac, cement circulated. Plug down at 8:30 P.M. April 12, 1961. Cement was allowed to set until 8:30 P.M. April 13, 1961 at which time the job was tested with 500 p.s.i. for thirty minutes with no pressure drop.




I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **ELLIOTT, INC.**

Address **Box 1355**

Roswell, New Mexico

By 
Title **Vice President**