


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. SP-076978
Unit Conservation Agreement



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

RECEIVED
OCT 23 1957
U. S. GEOLOGICAL SURVEY
SARASOTA, FLORIDA

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 17, 1957

Well No. SP-076978 is located 1870 ft. from [S] line and 1670 ft. from [E] line of sec. 15


SP-076978 Section 15 2-35-N 2-12-W N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Artesian New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5700 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was cased 9-30-57. Set 12" of 8 5/8" casing at 130' with 100 sacks cement. Tested for 30 minutes with 500# pressure, no leak. Drilled cement plug 12-8-57. Tested for 30 minutes with 500# pressure, no drop in pressure.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be conducted.

Company AMC OIL & GAS COMPANY
Address P O Box 706
Farmington, New Mexico
By Joe C. Salmon
Title District Superintendent

