UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

| · · · · · · · · · · · · · · · · · · · | Form Approved. Budget Bureau No. 42-R1424 |
|--|--|
| 5. LEASE | |
| Indian A | 11-ted 14-20-603-5036 |
| 6. IF INDIA | N, ALLOTTEE OR TRIBE NAME |
| Navajo | |
| 7. UNIT AG | REEMENT NAME |
| 0 51514 05 | |
| V 4. | R LEASE NAME |
| 9. WELL NO | prock L |
| 3 2 Ship | • • • |
| | R WILDCAT NAME |
| Shiproc | k-Gallup |
| 11. SEC., T., | R., M., OR BLK. AND SURVEY OR |
| AREA | |
| Sect. 1 | 7, T29N,R18W |
| | OR PARISH 13. STATE |
| San Juai | n N.M. |
| THE ACTINU. | |
| 15. FI FVATIO | ONS (SHOW DF, KDB, AND WD) |
| 5184.11 | • |
| ************************************** | • |
| | |
| Tanga terleting | |
| (NOTE: Repor | t results of multiple completion or zone |
| chang | re on Form 9-330.) |
| L. LY | |
| | |
| | |
| Il pertinent o | details and giv mertinent dates, |
| ctionally drille o this work.)* | ed, give subsurface scattons and |
| o unis work.)* | |
| | OIL CON. DIV. |
| | 011 2 1984 |
| | CON, |
| | DIST V. DIV |
| emented o | on top of casing |
| | _ |
| and we ha | ive no other knowledge |
| | |
| | |
| | |
| | |
| | |
| | Set @ Ft. |
| | |
| an DATE | 10/16/81 |
| DATE | |
| use) | |
| | |

FARAMA TOWN NEEDWOODE AREA

| | Navajo |
|--|--|
| SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different | 7. UNIT AGREEMENT NAME |
| reservoir. Use Form 9-331-C for such proposals.) | 8. FARM OR LEASE NAME |
| 1. oil ou gas | Shipingk I |
| well Well other | 9. WELL NO. |
| 2. NAME OF OPERATOR | 32 Shiprock 17 1 /X |
| Texas Eastern Developments Inc. | 10. FIELD OR WILDCAT NAME |
| 3. ADDRESS OF OPERATOR | 'I |
| P.O. Box 2521 Houston, Texas 77001 | Shiprock-Gallup |
| 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA |
| below.) AT SURFAC€263 F/SL and 370 F/EL | Sect. 17, T29N,R18W |
| AT TOP PROD. INTERVAL: | 12. COUNTY OR PARISH 13. STATE |
| AT TOTAL DEPTH: | San Juan N.M. |
| 16 CUECK APPROPRIATE DOV TO INDICATE MATURE | 14. API NO. |
| 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA | |
| REPORT, OR OTHER DATA | 15. ELEVATIONS (SHOW DF, KDB, AND WD) |
| REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: | 5184.11 |
| | PT TOP TOP PROPERTY AND A STATE OF THE STATE |
| TEST WATER SHUT-OFF | |
| SHOOT OR ACIDIZE | endi ^e |
| REPAIR WELL | |
| PULL OR ALTER CASING | (NOTE: Report results of multiple completion or zone change on Form 9-330.) |
| MULTIPLE COMPLETE | change on Form 9-330.) |
| CHANGE ZONES | e Mark V = − ↓ |
| ABANDON* | |
| (other) | |
| Well Cemented from TD to surface. 2" Marker (This information has been requested by USGS, or records on this well.) | O/L CON. DIV. cemented on top of casing |
| Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct SIGNED ON TO THE Field Technic (This space for Federal or State office) | tian DATE 10/16/8/ |
| APPROVED BY TITLE | DATE PACE PART PART PART PART PART PART PART PART |
| CONDITIONS OF APPROVAL, IF ANY: | AUUEFIED TON NELUKU |
| | |
| | JUN 111891 |
| | · 医乳腺素素 化二氯甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基 |