| Dec. 1973  |  | Budge  | et Bureau No. 42-R1424                         |
|--|--|--|--|
| UNITED STATES DEPARTMENT OF THE INTERIOR   |  | 5. LEASE   |  |
|  |  | SF-076465  |  |
|  | GEOLOGICAL SURVEY  | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME   |  |
| SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)  1. oil gas well |  | 7. UNIT AGREEMENT NAME   |  |
|  |  | 8. FARM OR LEASE NAM   | E j  |
|  |  | Beck "A"  9. WELL NO.  |  |
| well well other  2. NAME OF OPERATOR   |  | 9. WELL NO.   2  |  |
|  | Royalty Company  | 10. FIELD OR WILDCAT NAME  |  |
| 3. ADDRESS OF OPERATOR P.O. Drawer 570, Farmington, NM 87401   |  | Fulcher Kutz Pictured Cliffs  11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 10, T29N, R12W  |  |
| 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17   |  |  |  |
| below.)<br>AT SURFACE: 870' FNL & 790' FEL   |  | 12. COUNTY OR PARISH   |  |
| AT TOP PROD. INTERVAL: AT TOTAL DEPTH:   |  | San Juan   | New Mexico                                     |
|  |  | 14. API NO.  |  |
| 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA  |  | 15. ELEVATIONS (SHOW 5677' GR  | DF, KDB, AND WD)                               |
| REQUEST FOR  | APPROVAL TO: SUBSEQUENT REPORT OF:   | 3077 GR  |  |
| TEST WATER S FRACTURE TRE SHOOT OR AC REPAIR WELL PULL OR ALTE MULTIPLE CON CHANGE ZONE ABANDON*   | EAT  | (NOTE: Report results of muchange on Form 9-   | JAN 9 1981<br>OIL CON. COM.                    |
| (other) Spuc   | d and Casing Report X  | And the same and t | DIST. 3  |
| م محاليناهه:   | PROPOSED OR COMPLETED OPERATIONS (Clearly states stimated date of starting any proposed work. If well is dand true vertical depths for all markers and zones pertinent | lirectionally drilled, give Sub  | give pertinent dates;<br>surface locations and |
| 12/19/80   | Spudded 12-1/4" surface hole at 12:  | 30 P.M. 12-19-80   | and drilled to                                 |
|  | a Total Depth of 160'. Ran 3 joints (134') of 8-5/8", 24#, K-55  |  |  |
|  | casing set at 145'. Cemented with 140 sacks of Class "B" with 1/4#   |  |  |
|  | flocele per sack and % CaCl2. Plu  | g down at 5:30 P.I   | M. 12-19-80.                                   |
|  | Cement circulated to surface.  |  |  |
| 12/21/80   | Ran 59 joints (1837') of 2-7/8", 6.5   | #, K-55 casing set   | at 1848'.                                      |
|  | Cemented with 240 sacks of Class "I  | 3" 50/50 Poz with  | 6% gel followed                                |
|  | with 50 sacks of Class "B" with 2%   | CaCl <sub>2</sub> . Plug down  | at 5:30 AM 12-22-80                            |
| Subsurface Saf   | ety Valve: Manu. and Type  | Set  | @ Ft.  |
|  | ertify that the foregoing is true and correct  |  |  |
|  |  | k DATE 12-22-8   | 0  |
| SIGNED   | ACCEPTED FOR RECUITION Drilling Cler   | fice use)  |  |
| APPROVED BY _<br>CONDITIONS OF   | APPROVAL 1981 TITLE  | DATE   |  |