Denny S. Fout DEPUTY OIL & GAS INSPECTOR

DEC 22 1997

Approved

Meter Number:93956
Location Name:MOORE #6E
Location:TN-30 RG-08
SC-05 UL-J
2 - Federal
NMOCD Zone:OUTSIDE
Hazard Ranking Score:00

RECEIVED

APR 1 4 1997

OIL CON. DIV.

RATIONALE FOR RISK-BASED CLOSURE OF PRODUCTION PITS LOCATED OUTSIDE OF THE VULNERABLE ZONE IN THE SAN JUAN BASIN

This production pit location was ranked according to the criteria in the New Mexico Oil Conservation Division's Unlined Surface Impoundment Closure Guidelines and received a ranking score of zero. The estimated depth to groundwater is greater than 100-feet beneath ground surface (bgs), the pit is not in a well head protection area, and there are no surface water bodies within 1,000 horizontal feet of the pit location.

The primary source, discharge to the pit has been removed. There has been no discharge to the pits for at least 4 years and the pits have been closed for at least one year.

Each pit was backfilled with clean soil and graded in a manner to divert precipitation away from the excavated area. Minimal infiltration of rainfall is expected. Any rainfall that does infiltrate the ground surface must migrate through clean backfill before reaching the residual hydrocarbons.

There is no source material at the ground surface, so direct contact of hydrocarbons with livestock and the populous is not likely.

In general, outside of the vulnerable area and alluvial valleys, bedrock material is generally encountered within 20 feet of the ground surface. Bedrock material in the San Juan Basin consists of interbedded sandstones, shales and clays. According to Freeze and Cherry, 1979, the hydraulic conductivity of the bedrock material are as follows:

Sandstone 10^{-9} to 10^{-13} cm/sec Shale 10^{-12} to 10^{-16} cm/sec Clay 10^{-12} to 10^{-15} cm/sec

Based on this information, the residual hydrocarbons should not migrate to groundwater.

Natural process (bioremediation) are degrading the residual hydrocarbon to carbon dioxide and water and will continue until the source is gone, therefore minimizing any impact to the environment.

Based on the above information, it is highly unlikely that any source material will impact groundwater or ever find an exposure pathway to affect human health and therefore El Paso Field Services Company (EPFS) requests closure of this pit location.




FIELD PIT SITE ASSESSMENT FORM ELPASOFIELD SERVICES

| GENERAL | Meter: 93956 Location: Moore # 62 Operator #: 0203 Operator Name: Amoco P/L District: BloomField Coordinates: Letter: J Section 5 Township: 30 Range: 8 Or Latitude Longitude | | | | | | | |
|-----------------|---|--|--|--|--|--|--|--|
| | NMOCD Zone: (From NMOCD Maps) Inside Outside Land Type: BLM State (2) Fee (3) Indian Indian | | | | | | | |
| SITE ASSESSMENT | Depth to Groundwater Less Than 50 Feet (20 points) | | | | | | | |
| | Wellhead Protection Area: Is it less than 1000 ft from wells, springs, or other sources of fresh water extraction?, or; Is it less than 200 ft from a private domestic water source? (1) YES (20 points) (2) NO (0 points) | | | | | | | |
| | Horizontal Distance to Surface Water Body Less Than 200 Ft (20 points) | | | | | | | |
| | TOTAL HAZARD RANKING SCORE: O POINTS | | | | | | | |
| 3k (| Remarks: REDLINE : TOPO SHOW LOCATION OUTSIDE V.Z. THRES. PITS ON LOCATION DRIP PITS BELONG TO EPNG. WILL | | | | | | | |
| REMARL | CLOSE BOTH OF THEM. | | | | | | | |
| RE | the transfer was | | | | | | | |

ORIGINAL PIT LOCATION

Original Pit: a) Degrees from North 223 Footage from Wellhead 74'

b) Length: 18' Width: 18' Depth: 3'



| Remarks | : |
|---------|------|
| PUNTOS- | 1252 |

Completed By:

Signature

3.1.95

Date

FIELD PIT REMEDIATION/CLOSURE FORM

| GENERAL | Meter: 93956 Location: Moon + 6E Coordinates: Letter: T Section 5 Township: 30 Range: 8 Or Latitude Longitude Date Started: 5/1/95 Run: 10 32 |
|--------------------|--|
| FIELD OBSERVATIONS | Sample Number(s): Ko410 Sample Depth: 12' Feet Final PID Reading 3700 PID Reading Depth Feet Yes No Groundwater Encountered Approximate Depth Feet |
| CLOSURE | Remediation Method: Excavation |
| REMARKS | Remarks: Dytest Hole to 12', Took Dip Sample, Closed |
| | Signature of Specialist: My Jan |



FIELD SERVICES LABORATORY ANALYTICAL REPORT

PIT CLOSURE PROJECT - Soil Samples Outside the GWV Zone

SAMPLE IDENTIFICATION

| | Field | ID | | Lab ID | | | |
|----------------------------|-------------------------|----------------|------------|--|--------------|-------|--|
| SAMPLE NUMBER: | K10 4 | 946776 | | | ı | | |
| MTR CODE SITE NAME: | 9395 | N/A | | | ı | | |
| SAMPLE DATE TIME (Hrs): | 5-1-4: | 14.15 | | | ı | | |
| SAMPLED BY: | | N _i | /A | | | | |
| DATE OF TPH EXT. ANAL.: | 5/4/9 | S | c/4/9s | | | | |
| DATE OF BTEX EXT. ANAL.: | NIA | | | l A | | | |
| TYPE DESCRIPTION: | PE DESCRIPTION: | | | 46HT PROWN STURY SHAY | | | |
| REMARKS: | | RESULTS | | | | | |
| PARAMETER | RESULT UNITS QUALIFIERS | | | | · | | |
| | | | DF | <u> Q</u> | M(g) | V(ml) | |
| | | | 1 1 | | 1 1 | | |
| TPH (418.1) | 47.1 | MG/KG | | | 10. J. | 28 | |
| TPH (418.1) HEADSPACE PID | 3 | MG/KG PPM | | | 200 | 28 | |
| | | - | | | in Section 1 | | |
| HEADSPACE PID | 3 24.6 | PPM | 1418.1 | | in Section 1 | | |
| HEADSPACE PID | 3 24.6 | PPM % | i 418.1 ·- | 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1 | Take 1 | | |

********************** Test Method for Oil and Grease and Petroleum Hydrocarbons in Water and Soil

> Perkin-Elmer Model 1600 FT-IR Analysis Report

5/05/04 11:11


Sample identification 46776

roitial mass of sample, 9

Volume of sample after extraction, ml :8.ÖÖ

- Patroleum hydrocarbons, ppm 19.030

Not absorbance of hydrocarbons (2930 cm-1) s, order



*