UNITED STATES

UNITED STATES DEPARTMENT OF THE INTERIOR	5. LEASE SF-079907
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME Gallegos Canyon Unit 8. FARM OR LEASE NAME
1. oil gas X other	9. WELL NO. 2013 4 7 7 7 8
2. NAME OF OPERATOR Amoco Production Company	145E 3 3 5 5 10. FIELD OR WILDCAT NAME 3 5 5
3. ADDRESS OF OPERATOR 501 Airport Drive Farmington, NM 87401	Basin Dakota 333
4. LOCATION OF WELL (REPORT LOCATION CLEARLY See space 17 below.) 790' FNL X 990' FWL AT SURFACE: Section 26, T29N, R12W AT TOP PROD. INTERVAL: same AT TOTAL DEPTH: same	AREA NW/4, NW/4 Section 26, T29N, R12W 12. COUNTY OR PARISH 13. STATE San Juan New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	14. API NO. 30-045-24291 15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF	(NOTE: Report results of multiple completion or zone change on Form 9-330.) e all pertinent details, and give pertinent dates, rectionally drilled, give subserface locations and to this work.)* Total depth of the well is 6229', ervals from 6074' to 6114' and 38" holes. Sand-water fraced
Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct SIGNED	U. S. GEOLOGICAL SURVEY FARMINGTON, N. M. Set @ Ft.
(This space for Federal or State office APPROVED BYTITLE	นดายกระท ยังกับ กะคุณก