

06

District I _____	State Of New Mexico	SUBMIT 1 COPY TO
P.O. Box 1980, Hobbs, NM	Energy, Minerals and Natural Resources Department	APPROPRIATE
District II _____		DISTRICT OFFICE
P.O. Drawer, Artesia, NM 88211	OIL CONSERVATION DIVISION	AND 1 COPY TO
District III _____	P.O. Box 2088	SANTA FE OFFICE
1000 Rio Brazos Rd. Aztec, NM 87410	Santa Fe, New Mexico 87504-2088	(Revised 3/9/94)

PIT REMEDIATION AND CLOSURE REPORT

Operator: <u>Conoco Inc.</u>		Telephone: <u>505-324-5846</u>	
Address: <u>3315 Bloomfield Hwy - Farmington, NM 87401</u>			
Facility Or: <u>Houck Com 1-E</u>			
Well Name _____			
Location:	Unit or Qtr/Qtr Sec	<u>M</u> Sec <u>1</u> T <u>29N</u> R <u>10W</u> County <u>San Juan</u>	
Pit Type:	Separator <u>X</u>	Dehydrator _____	Other _____
Land Type:	BLM <u>X</u> State _____	Fee _____	Other _____
Pit Location: (Attach diagram)	Pit dimension:	length <u>6'</u>	width <u>6'</u> depth <u>4'</u>
	Reference:	wellhead <u>X</u>	other _____
	Footage from reference:	<u>78'</u>	
	Direction from reference:	<u>120</u> Degrees <u>X</u> East of _____ North	West <u>X</u> South

Depth To Ground Water: (Vertical distance from contaminants to seasonal high water elevation of ground water)	Less than 50 feet	(20 points)	
	50 feet to 99 feet	(10 points)	
	Greater than 100 feet	(0 points)	
	Total		<u>0</u>
Wellhead Protection Area: (Less than 200 feet from a private domestic water source, or; less than 1000 feet from all other water sources)	Yes	(20 points)	
	No	(0 points)	
	Total		<u>0</u>
Distance To Surface Water: (Horizontal distance to perennial lakes, ponds, rivers, streams, creeks, irrigation canals and ditches)	Less than 200 feet	(20 points)	(20 points)
	200 feet to 1000 feet	(10 points)	(10 points)
	Greater than 1000 feet	(0 points)	(0 points)
	Total		<u>0</u>
RANKING SCORE (TOTAL POINTS):			<u>0</u>



Date Remediation Started:		No Remediation Necessary		Date Completed:	
Remediation Method:		Excavation:		Approx. cubic yards	
(Check all appropriate sections)		Landfarm		Insitu Bioremediation	
		Other			
Remediation Location:		Onsite		Offsite	
(ie. landfarmed onsite, name and location of offsite facility)					
General Description Of Remedial Action:					
Ground Water Encountered:		No	X	Yes	Depth
Final Pit:		Sample location		Center of pit bottom	
Closure Sampling:					
(if multiple samples attach sample results and diagram of sample locations and depths)		Sample depth		3' below bottom center of pit	
		Sample date		4/25/2001	Sample time 3:40 PM
		Sample Results			
		Benzene (ppm)		ND	
		Total BTEX (ppm)		ND	
		Field headspace (ppm)		N/A	
		TPH		ND	
Ground Water Sample:		Yes		No	X
				(If yes, attach sample results)	
I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF					
DATE		9/6/01		PRINTED NAME John E. Cofer	
SIGNATURE		John E. Cofer		AND TITLE Environmental Coordinator	

ENVIROTECH LABS

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client:	Conoco	Project #:	97070-003-296
Sample ID:	Vent Pit	Date Reported:	04-27-01
Laboratory Number:	19792	Date Sampled:	04-25-01
Chain of Custody:	8628	Date Received:	04-26-01
Sample Matrix:	Soil	Date Analyzed:	04-27-01
Preservative:	Cool	Date Extracted:	04-27-01
Condition:	Cool & Intact	Analysis Requested:	BTEX

Parameter	Concentration (ug/Kg)	Det. Limit (ug/Kg)
Benzene	ND	1.8
Toluene	ND	1.7
Ethylbenzene	ND	1.5
p,m-Xylene	ND	2.2
o-Xylene	ND	1.0
Total BTEX	ND	


ND - Parameter not detected at the stated detection limit.


Surrogate Recoveries:	Parameter	Percent Recovery
	Fluorobenzene	100 %
	1,4-difluorobenzene	100 %
	Bromochlorobenzene	100 %

References: Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Method 8021B, Aromatic Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Comments: Houck Com 1 - E Non-Vulnerable.


Analyst


Review

ENVIROTECH LABS

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

EPA METHOD 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons


Client:	Conoco	Project #:	97070-003-296
Sample ID:	Vent Pit	Date Reported:	04-27-01
Laboratory Number:	19792	Date Sampled:	04-25-01
Chain of Custody No:	8628	Date Received:	04-26-01
Sample Matrix:	Soil	Date Extracted:	04-27-01
Preservative:	Cool	Date Analyzed:	04-27-01
Condition:	Cool and Intact	Analysis Requested:	8015 TPH


Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	ND	0.2
Diesel Range (C10 - C28)	ND	0.1
Total Petroleum Hydrocarbons	ND	0.1

ND - Parameter not detected at the stated detection limit.

References: Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.



Comments: Houck Com 1 - E Non-vulnerable.


Analyst


Review

CHAIN OF CUSTODY RECORD

08628

Client / Project Name		Project Location		ANALYSIS / PARAMETERS																					
CONOCO		Houck Com I-E																							
Sampler:				Client No.																					
Tye Johnson		97070-003-216																							
Sample No./ Identification	Sample Date	Sample Time	Lab Number	Sample Matrix	No. of Containers	TPH	BTEX						Remarks												
Vent Pit	4/25/01	3:40p	R792	Soil	1	X	X						Non-vulnerable												
Tank Drain	4/25/01	3:30p	19793	Soil	1	X	X						Non-vulnerable												
Relinquished by: (Signature)		Date		Time		Received by: (Signature)		Date		Time															
		4/26/01		8:40a				4/26/01		8:40p															
Relinquished by: (Signature)						Received by: (Signature)																			
Relinquished by: (Signature)						Received by: (Signature)																			
ENVIROTECH INC. 5796 U.S. Highway 64 Farmington, New Mexico 87401 (505) 632-0615																									
Sample Receipt <table border="1"> <tr> <td>Y</td> <td>N</td> <td>N/A</td> </tr> <tr> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="3">Received Intact</td> </tr> <tr> <td colspan="3">Cool - Ice/Blue Ice</td> </tr> </table>														Y	N	N/A				Received Intact			Cool - Ice/Blue Ice		
Y	N	N/A																							
Received Intact																									
Cool - Ice/Blue Ice																									

CHAIN OF CUSTODY RECORD

08628

Client / Project Name		Project Location		ANALYSIS / PARAMETERS										
Conoco		Houck Com 1-E												
Sampler: <i>Tex Johnson</i>		Client No. <i>97070-003-</i>												
Sample No./ Identification	Sample Date	Sample Time	Lab Number	Sample Matrix	No. of Containers						Remarks			
Vent Pit	4/25/01	3:40p		Soil	1	X	X						Non-vulnerable	
Tank Drain	4/25/01	3:30p		Soil	1	X	X						Non-vulnerable	
Relinquished by: (Signature)	<i>[Signature]</i>	Date	Time	Received by: (Signature)									Date	Time
Relinquished by: (Signature)	<i>[Signature]</i>	4/26/01	8:40a	<i>[Signature]</i>									4/26/01	7:40a
Relinquished by: (Signature)				Received by: (Signature)										
Relinquished by: (Signature)				Received by: (Signature)										

ENVIROTECH INC.

5796 U.S. Highway 64
Farmington, New Mexico 87401
(505) 632-0615

Sample Receipt

Received Intact	Y	N	N/A
Cool - Ice/Blue Ice			

