

7-27-88

30-045-26988

F

F. Loc. 1100/S; 1035/E Elev. 5852 GL Spd. Cu. ft. ID Cu. ft. P8
@ W Sx. Int. @ W Sx. I. @
Lossing S. Prod. Stim. 1st Del. Gas
Log Perf. Grav. 1st Del. Oil

BO/D		Hrs.		SICP		PSI After		Days GOR		TEST DATA						Ref. No.
TOPS	MCF/D After	NIID X	Well Log	Schd	PC	Q	PW	PD	D							
Ojo Alamo		C-103	Pict X													
Kirtland		C-104	Electric Log													
Fruitland			C-122													
Pictured Cliffs		Ditr	Dfo													
Chacra		Datr	Doc													
Cliff House																
Menefee																
Point Lookout																
Mancos																
Gallup																
Greenhorn																
Dakota																
Entrudo																
Tenneco										Acres	160					

Indes. Fr. Coal Co. SJ S 21 T 30N R 8W U P Oper. Amoco Production Co. Lee. Patterson No. 5

ABANDONED LOCATION SF-078040 et al. (WC)
3162.3-1(F) (019)

AUG. 17 1989

CERTIFIED--RETURN RECEIPT REQUESTED
P-117-127-244

Amoco Production Company
2325 East 30th Street
Farmington, NM 87401

Gentlemen:

Enclosed are your Applications for Permit to Drill (APD) for well No. 8B Mudge LS, NW/4NE/4 sec. 12, T. 31 N., R. 11 W., San Juan County, New Mexico, lease SF-078040 and well No. 5 Patterson, SE/4SE/4 sec. 21, T. 30 N., R. 8 W., San Juan County, New Mexico, lease SF-078578. As discussed with Cindy Burton of your company on August 10, 1989, the subject APDs are rescinded and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

Dail R. Keller

FOR

Ron Fellows
Area Manager

Enclosures

cc: NMOCC, Aztec, NM

RECEIVED

AUG 21 1989

OIL CON. DIST.
DIST. 3