

MERRION

OIL & GAS

FARMINGTON A COM No. 1E

API #30-045-29626

Section 14, T29N, R13W

San Juan County, New Mexico

SLOPE TESTS

	<u>Depth</u>	<u>Hole Deviation</u>
#1	153'	1/2°
#2	369'	3/4°
#3	755'	3/4°
#4	1281'	1/2°
#5	1772'	3/4°
#6	2252'	3/4°
#7	2782'	3/4°
#8	3233'	1/2°
#9	3533'	3/4°
#10	4033'	1°
#11	4560'	3/4°
#12	5063'	1-1/4°
#13	5539'	1-3/4°

DEC 21 1998
OIL CON. DIV.
DIST. 3


I, Steven S. Dunn, being first duly sworn, depose and state that the attached and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.



Steven S. Dunn

Subscribed and sworn before me this 21st day of December, 1998

State of New Mexico }
 } ss
County of San Juan }



Esther J. Greyeyes
Notary Public

My Commission Expires: August 7, 2002