



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 37 07530-1
Unit R/2 of Sec. 5

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	X
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 1 is located 1105 ft. from N line and 550 ft. from E line of sec. 5
NE/4 Sec. 5 (1/4 Sec. and Sec. No.) 30N (Twp.) 8W (Range) 107W (Meridian)
Blanco (New Mexico) (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6271 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well Spudded May 4, 1956

Drilled to TD 105' cemented to 150' Set 4 jts., 123' of 10 3/4 32.75# Elect-Bolt Casing, landed at 136' cemented w/ 150 sacks. Casing was pressured to 500# for 1 hour with no drop in pressure. After cement set, plug was drilled and run on B.O.P. were closed and casing pressured to 500# for 30 minutes with no appreciable drop in pressure. Drilling ahead was resumed.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations are begun.

Company Bell-Taylor Oil Corporation

Address P. O. Box 1175

Farmington, New Mexico

By [Signature]

Title Dist. Supt.



