

TABULATION OF DEVIATION TESTS

TENNECO OIL COMPANY

FLORANCE #37

<u>DEPTH</u>	<u>INCLINATION</u>		
4575'	1°		
4589'	3-3/4°	1.0	
4603'	6-1/2°	1.0	
4638'	6-3/4°	4.0	3.7
4716'	6-1/2°	2.0	1.7
4917'	5-1/4°	1.0	1.0
5224'	3-1/4°	1.0	1.0
5493'	2-1/2°	1.0	1.0
5767'	1-1/2°	2.8	1.7
6064'	3°	3.0	1.7
6123'	4-1/2°	6	4.7
6242'	5°	12.0	12.0
6334'	5-1/4°	7	6.7
6423'	5-1/2°	7	6.7
6574'	5-3/4°	15	15
6663'	6-1/4°	7	6.7
6754'	6°	10	10
7023'	4-3/4°	4.5	4.5
7123'	4-3/4°	4.5	4.5
7203'	4-3/4°	4.5	4.5
7294'	4-1/4°	9.0	6.7

A F F I D A V I T

THIS IS TO CERTIFY that to the best of my knowledge the above tabulation details the deviation test taken on TENNECO OIL COMPANY'S Florance #37, Blanco M.V. and Basin Dakota Field, located in Section 6, T-30-N, R-8-W, San Juan County, New Mexico.

Signed [Signature]
District Production Engineer

THE STATE OF COLORADO)
COUNTY OF LA PLATA)



BEFORE ME, the undersigned authority, on this day personally appeared J. D. Hicks known to me to be District Production Engineer for Tenneco Oil Company and to be the person whose name is subscribed to the above statement, who, being by me duly sworn on oath, states that he has knowledge of the facts stated herein and that said statement is true and correct.

SUBSCRIBED AND SWORN TO before me, a Notary Public in and for said County and State this 24th day of June, 1965.

Mary Anne Chapman