Form 9-231 (May 1963)	UNITED STATES SUBMIT DEPARTMENT OF THE INTERIOR VOISE AND GEOLOGICAL SURVEY	Porm approved. Instructions on relation on relation and select ST 07899
SUI	NDRY NOTICES AND REPORTS ON WELL s form for proposals to drill or to deepen or plug back to a difference use "APPLICATION FOR PERMIT—" for such proposals.)	S 6. IF INDIAN, ALLOTTEE OR THE NAME
OIL GAS WELL X OTHER		7. UNIT AGREEMENT NAME San Juan 31-6 Unit 8. FARM OR LEASE NAME
2. NAME OF OPERATOR El Paso Na 3. ADDRESS OF OPERAT	tural Gas Company	San Juan 31-6 Unit
	, Farmington, NM 87401 (Report location clearly and in accordance with any State requirem 1470'S, 1490'W	Basin Dakota 11. sec., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 27, T-31-N, R-6-W
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GE, etc.) 6454 GL	Rio Arriba NAI
TEST WATER SHUT FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL	MULTIPLE COMPLETE FRACTUL ABANDON* SHOOTIL CHANGE PLANS (Other)	SUBSEQUENT REPORT OF: SHUT-OFF X REPAIRING WELL RE TREATMENT ALTERING CASING ABANDONMENT*
(Other) 17. DESCRIBE PROPOSED proposed work, nent to this work. 10-31-73	OR COMPLETED OPERATIONS (Clearly state all pertinent details, and If well is directionally drilled, give subsurface locations and measurements.)	Norm: Report results of multiple completion on Well ompletion or Recompletion Report and Log form.) give pertinent dates, including estimated date of starting any ured and true vertical depths for all markers and zones pertined.
11-1-73	Ran 10 joints 9 5/8", 32.3#, H-40 surface Cemented with 342 cu.ft. cement, circula Held 600#/30 minutes.	