

<u>DEPTH</u>	<u>DEVIATION</u>	<u>DEPTH</u>	<u>DEVIATION</u>
58'	1/2°	4549'	1/4°
305'	3/4°	4947'	1/2°
867'	1/2°	5441'	1/2°
1102'	1/2°	5826'	1/4°
1392'	1/4°	5870'	1/2°
1621'	3/4°	6338'	1/2°
2300'	1/2°	6730'	3/4°
2597'	3/4°	6988'	1°
2909'	1-1/4°	7430'	1°
3151'	3/4°	7675'	3/4°
3379'	1°	7990'	3/4°
3755'	1/4°	8022'	1°
3828'	1/2°	8116'	1-1/4°
3978'	3/4°	8280'	3/4°
4074'	1/2°		

THIS IS TO CERTIFY that to the best of my knowledge the above tabulation details the deviation tests taken on AMOCO PRODUCTION COMPANY'S Rosa Unit No. 55 located 1510' FSL and 1170' FEL Section 34, T-31-N, R-5-W, Rio Arriba County, New Mexico.

THE STATE OF NEW MEXICO) )  
COUNTY OF SAN JUAN ) ) SS.

Clarence J. Brown  
Notary Public

My Commission Expires: December 28, 1975