

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	k
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

5a. Indicate Type of Lease

State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR RE-DRILL OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Dugan Production Corp.	8. Farm or Lease Name Willow Creek
3. Address of Operator Box 234, Farmington, New Mexico 87401	9. Well No. 1
4. Location of Well UNIT LETTER <u>K</u> , <u>1480</u> FEET FROM THE <u>South</u> LINE AND <u>1800</u> FEET FROM THE <u>West</u> LINE, SECTION <u>30</u> TOWNSHIP <u>IN</u> RANGE <u>2E</u> NMPM. M&B Survey	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 8045' GR	12. County Rio Arriba

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-18-74

Spudded 3:00 PM, 10-17-74. Drilled 8-3/4" hole to 76' with air.

10-19-74

Could not get 7" casing down. Reamed top 12' hole to 12-1/4" thru boulders. Cleaned out 8-3/4" hole. Ran 2 jts 7" OD 20# J-55 8R ST&C casing set at 78' RKB. Cemented with 11 sx. Good cement to surface. Job complete 11:00 AM, 10-18-74.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Original signed by T. A. Dugan TITLE Engineer DATE 10-24-74
Thomas A. Dugan
 APPROVED BY [Signature] TITLE SUPERVISOR DIST. #3 DATE 10-25-74
 CONDITIONS OF APPROVAL, IF ANY: