UNITED STATES

UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	C
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	Rosa Unit 9 76
reservoir. God Form's God-G for South proposation,	8. FARM OR LEASE NAME 19 5 CARD
1. oil gas x other	
2. NAME OF OPERATOR	9. WELL NO. 9 1 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
AMOCO PRODUCTION COMPANY	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Basin Dakota
501 Airport Drive Farmington, NM 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY, See space 17	AREA NE/4 NE/4 Section 17,
below.) 1140' FNL x 860' FEL, Section 17,	T-31-N, R-5-W = = ₹ ₹ ₹
AT SURFACE: T-31-N, R-5-W AT TOP PROD. INTERVAL: Same	12. COUNTY OR PARISH 13. STATE
AT TOTAL DEPTH: Same	Rio Arriba = 2 NM = 5
Same 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.	14. API NO. 플루부 크 현 필요 중 30-039-21702 등 표표 표표
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	6295 GL & 2 2 6 6
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
FRACTURE TREAT	trogat bridge company bridge company bridge company be company by the company by
SHOOT OR ACIDIZE	gar brid 12 yris 13 yris 15 yris 15 brid 15 brid 16 br
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING []	change on Form 9–330,) σ ≒ ਪੱਲ 🖹
MULTIPLE COMPLETE	raoii dista
ABANDON*	oitount sago lices sago lices and test and test and the dark of th
other) Spud & Set Casing	erroitsusten obsesses to be steeded to be of bediend to bediend to the did the di assesses to see to
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state	
including estimated date of starting any proposed work. If well is di	rectionally drilled, give subsurface locations and
measured and true vertical depths for all markers and zones pertinen	
Spudded 15" hole on 7/14/78. Drilled to 310' & set at 309'. Cemented with 315 sx Class "B	. set 10-3/42; 40.3%; k-35 casing
ment. Pressure tested to 800 psi: held OK.	Reduced holes to 9-7/8" and drilled
ment. Pressure tested to 800 psi; held OK. to 3654'. Ran 7-5/8" 26.4# K-55 casing & set Class "B", 50:50 Poz, 6% gel, 2# Tuf Plug per	at 3653'. Femented with \$1000 sx
Class "B", 50:50 Poz, 6% gel, 2# Tuf Plug per	sx. Followed with 100 sx Class
"B" Neat.* Pressure tested to 1000 psi; held	OK. Reduced hole to 6-3/4 and
drilled to 8037'. Ran 4-1/2", 11.6#, P-110 c	asing & set at 20037 ? Cemented with
880 sx Class "B", 50:50 Poz, 6% gel, 2# Tuf P	lug per sx f Followed with 100 sx
Class "B" Neat. Circulated entire job.	Disk the control of t
P: 1 016/70	
Rig released on 8/6/78.	A Library of Santa
1	
* Circulated good cement. Subsurface Safety Valve: Manu. and Type	timing to the suggest of the state of the suggest of the
1	AUG 14 19代表 高 高 高
18. I hereby <u>certify</u> that the folegoing is true and correct	DIST. 3 A SECTION AS S
SIGNED E. E. SVOBODA TITLE Area Adm. Sup	VA DATE 8/9/78
(This space for Federal or State office	
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	DATE TO THE TOTAL OF THE TOTAL
CONDITIONS OF AFFROYAG II ANT.	自治智可理制制和

*See Instructions on Reverse Side