takkin 13WE 19WE

SF*078767

5. LEASE

UNITED STATES DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOITEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME & & & & & & & & & & & & & & & & & & &
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	Rosa Unit 5 7 5 7 7 8 8 FARM OR LEASE NAME 5 98 7
1. oil gas 🗵 other	
2. NAME OF OPERATOR	S 66.55 S S S S S S S S S S S S S S S S S S
AMOCO PRODUCTION COMPANY	10. FIELD OR WILDCAT NAME Basin Dakota
3. ADDRESS OF OPERATOR	Basin Dakota
501 Airport Drive Farmington, NM 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA NW/4 SW74 Section 13,
below.) 1960' FSL x 815' FWL, Section 13,	T-31=N, R-6=W = = = = = = = = = = = = = = = = = =
AT SURFACE: T-31-N, R-6-W AT TOP PROD. INTERVAL: Comp	12. COUNTY OR PARISH 13. STATE
AT TOTAL DEPTH. Same	Rio Arriba - NM NT
Same 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	I
REPORT, OR OTHER DATA	30-039-21758 ====================================
	6346 GL 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	0040 30
TEST WATER SHUT-OFF	555° a -6556
FRACTURE TREAT 📙 📙	an bine to top you to top or to
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING [change on Form 0 330 F F F
MULTIPLE COMPLETE	enoibunteation per province of the common of
CHANGE ZONES	प्रदेश हैं हैं। जिस्सार के किस्सार जिस्सार के किस्सार के किस
(other) Completion-Perf & Frac	និ ស្ត្រីស្ត្រី មិន្ត្រីក្នុង អូ
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinen Completion operations commenced on 7/27/78.	irectionally drilled, give subsurface locations and it to this work.)*
Logged cement and drilled cement to 8070'. S	Set bridge plug at 8070 PBD.
Pressure tested casing to 8500 psi; held OK.	Perforated 8032-8058. Fraced
with 73,000 lbs. sand and 32,000 gallons frac	fluid. Set drillable bridge
plug at 8010'. Pressure tested to 5,000 psi;	held OK. Perforated 7913-7984
Fraced with 305,000 lbs. sand and 115,000 gal	lons frac fluid ្ទ Tripped in
with tubing and bit. Cleaned out sand and fr	
and cleaned out to 8070'. Production tubing	5 # N # N # N # N # N # N # N # N # N #
0 1	wat I
Completion rig released on 8/8/78.	submite and has been the state of the state
	The state of the s
Subsurface Safety Valve: Manu. and Type	TOIL COME SM. THE FILE
18. I hereby certify that the foregoing is true and correct	DISTER PROPERTY
Area Adm. Sur	ovr. 28/9/8 5 55 1
(This space for Federal or State off	ice use) The same of the same
APPROVED BY TITLE	DATE DATE
CONDITIONS OF APPROVAL, IF ANY:	
	model in a series
*See Instructions on Reverse S	AUG 1 0 1078

AUG 1 0 15/3

U. S. REDLORICAL SURVEY