TABULATION OF DEVIATION TESTS ROSA UNIT NO. 66 AMOCO PRODUCTION COMPANY

DEPTH	•		DEVIATION
314'		<u>.</u>	1/2°
695'			3/4°
1002'			1°
1593'			ī°
1699'			1-1/2°
2212'			1-3/4°
2486'			1-1/4°
2985 '			3/4°
3355 '			1/4°
40 30 '			1°
45481			3°
4763 ¹			3-1/2°
4963'	•		3-3/4°
5228 '			3-3/4-4°
5384 '			3-1/2°
5842 '			3-1/4°
6375 '			4°
6872 '			4-1/4°
7804 '			2°
7868 '			1-1/2°

AFFIDAVIT

THIS IS TO CERTIFY that to the best of my knowledge the above tabulation details the deviation tests taken on AMOCO PRODUCTION COMPANY'S Rosa Unit No. 66 located 1960' FSL x 815' FWL, NW/4, SW/4, Section 13, T-31-N, R-6-W, Rio Arriba County, New Mexico.

Signed Jobboaco Title Dist. Adm. Supvervisor

THE STATE OF NEW MEXICO)		
COUNTY OF SAN JUAN)	SS.	1
DEFORE ME the understance		
BEFORE ME, the undersigned appeared <u>E. E. Svoboda</u>	known	to me to be bear wan
Supvr. for Amoco Produ	uction Company and	to be the person
Supvr. for Amoco Produ whose name is subscribed t me duly sworn on oath, sta	to the above statem ates that he has kn	owledge of the facts
stated herein and that sai	id statement is tru	e and correct.
SUBSCRIBED AND SWORN TO be		
County and State this	3rd day of N	lovember , 19 <u>78</u> .
	0	. 7 .
	$\mathcal{L}_{\mathcal{L}}$	20