TABULATION OF DEVIATION TESTS

AMOCO PRODUCTION COMPANY

DEPTH		DEVIATION	
895' 1592' 2085' 2323' 2834' 3365' 3865' 4312' 4837' 5299' 5803' 6335' 6867' 7399' 7729'		3/4° 1/4° 1/2° 1° 3/4° 3/4° 3/4° 1° 1° 1/2° 1/2° 1/2° 1/2° 3/4° 3/4° 3/4° 3/4°	
8085'	<u>A F F I D A V I T</u>	3/4°	MOV 0 8 1984 L COM. DIV. DIST. 3

A F F I D A V I T

THIS IS TO CERTIFY that to the best of my knowledge the above tabulation details the deviation tests taken on AMOCO PRODUCTION

COMPANY'S Rosa Unit 99Y, Section 26, T31N, R6W, Rio Arriba County New Mexico.
Signed BDSLaw
TitleAdmin. Supervisor
THE STATE OF NEW MEXICO) SS. COUNTY OF SAN JUAN)
BEFORE ME, the undersigned authority, on this day personally appeared B.D. Shaw known to me to be Admin. Supervisor for Amoco Production Company and to be the person whose name is subscribed to the above statement, who, being by me duly sworn on oath, states that he has knowledge of the facts stated herein and that said statement is true and correct.
SUBSCRIBED AND SWORN to before me, a Notary Public in and for said County and State this day of, 19
Notary Public

My Commission Expires: June 16, 1985