

UNITED STATES
DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Auto Development Co.

234 Petroleum Club Plaza, Farmington, New Mexico

Well No. 1, 1000 ft. deep, located in the Greenhorn section, 10 miles north of Farmington, New Mexico. The well is currently producing oil at a rate of 100 barrels per day.

1100/S 2000/S

3771


Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NATURE OF NOTICE, REPORT, OR OTHER DATA		NATURE OF NOTICE, REPORT, OR OTHER DATA	
1. NEW WELL	2. REPAIR WORK	3. PRODUCTION TEST	4. OTHER
5. ABANDONMENT	6. RE-ENTRY	7. RE-ENTRY	8. RE-ENTRY
9. RE-ENTRY	10. RE-ENTRY	11. RE-ENTRY	12. RE-ENTRY

When filling out this form, please indicate all pertinent details, including the location of the well, the nature of the work, and the results of the work.

Repair casing leaks w/packer and Kan-Pec chemicals, as follows:

Run up workover rig, circulate out mud, sand and shale to T.O. Circulate until hole is clean. PCH. Run Baker Model "D" production packer on wire line. Set just below Greenhorn section w/hump out plug to keep any water up Kan-Pec water from getting below packer. GIN w/thg., Model "D" locator and tail pipe. Set Kan above Model "D", set tail pipe down on hump out plug, run tail pipe through loc. and land locator seals in packer. Flange up well head, wash well in and re-test if necessary.



Check appropriate box to indicate nature of notice, report, or other data.

Auto Development Co.

TITLE

Well No. 1, 1000 ft. deep, located in the Greenhorn section, 10 miles north of Farmington, New Mexico.

3771

1100/S 2000/S

TITLE

