


ILLEGIBLE

(SUBMIT IN TRIPLICATE)

Land Office Santa Fe

Lease No. 078106

Unit _____



UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	X		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

New Mexico Federal "K" _____ May 2, 1963

Well No. 3 is located 1980 ft. from N line and 660 ft. from W line of sec. _____

NW 1/4 of SW 1/4 of Sec. 35 T10N-R15W W11E
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Undesignated San Juan New Mexico
(Township) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5139 ft.

DETAILS OF WORK


(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well is now pumping lead oil at 2 BPD rate. We propose to pull rods and tubing, set 5-1/2" casing at 1200' and pull casing.

Bottom cement plug from 1500' to 1600' PSTD (Perf at 1592)

Second cement plug from 3150 to 3300, third cement plug in top of surface pipe,

Install marker and clean location.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Sunray Oil Company

Address 200 Petroleum Club Plaza

Farmington, New Mexico

By E. P. Ramsey

Title District Manager