## TABULATION OF DEVIATION TESTS

## TENNECO OIL COMPANY

## FLORANCE 44

DEPTH	INCLINATION
4059	3-3/4°
4080	1/4°
4096	20
4104	3-3/4°
4119	
4145	3-1/4° 1/2°
4219	1/20
4237	3-1/25
4482	1-1/40
4573	20
4998	1-1/4° 1/4° 1/4°
5305	1/40
5608	1/4
5794	10
6007	3/40
6189	₹/11~
6341	3/4° 0° 1/2°
6492	000
6707	1/2*

## AFFIDAVIT

THIS IS TO CERTIFY that to the best of my knowledge the above tabulation details the deviation test taken on TENNECO OIL COMPANY'S Florance 44, Blanco Mesaverde-Dakota Field, located in Section 31, T-30-N, R-8-W, San Juan County, New Mexico.

THE STATE OF COLORADO)
SS.
COUNTY OF LA PLATA

BEFORE ME, the undersigned authority, on this day personally appeared J. D. Hicks known to me to be District Production Engineer for Tenneco Oil Company and to be the person whose name is subscribed to the above statement, who, being by me duly sworn on oath, states that he has knowledge of the facts stated herein and that said statement is true and correct.

SUBSCRIBED AND SWORN TO before me, a Notary Public in and for said County and State this 3rd day of June, 1965.

Many lune Oleaguan

Production Engir