

6 DECS

1 Sample - Durango

1 Touchstone

1 Earl Rogers

1 File

(SUBMIT IN TRIPLICATE)

UNITED STATES

DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

Indian Agency Navajo

Allottee \_\_\_\_\_

Lease No. 14-20-603-2012


## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

U. S. GEOLOGICAL SURVEY  
HUNTINGTON, NEW MEXICO  
MAY 15 1962

Well No. Navajo 1-32 is located 660 ft. from [N] line and 1900 ft. from [E] line of sec. 32

1/4 32 (1/4 Sec. and Sec. No.) 30N (Twp.) 16W (Range) 100M (Meridian)  
Wildcat (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the ground level above sea level is 5294 ft.

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud 5-5-62. Ran 3 jts 7", 20', J-55 Csg., T.E. 92' set at 104' w/50 sz  
P.O.B. at 3:00 PM 5-5-62.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced

Company Blake Touchstone

Address 475 Huntington Drive

San Marino, California

Original signed by T. A. Dugan  
By \_\_\_\_\_

Title Consulting Engineer