14-20-603-4909

5. LEASE

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
GEOLOGICAL SURVEY	Navajo
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME
	Horseshoe Gallup Unit
	8. FARM OR LEASE NAME
	Horseshoe Gallup Unit
1. oil gas well cther X - Injection	9. WELL NO. 250
2. NAME OF OPERATOR ARCO Oil & Gas Co., Div. of Atlantic Richfield Company	10. FIELD OR WILDCAT NAME Horseshoe Gallup Unit
3. ADDRESS OF OPERATOR 707-17th Street,	
P.O. Box 5540, Denver, CO 80217	11. SEC., T., R., M., OR BLK, AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) Unit "L"	AREA Sec. 2-30N-16W
AT SURFACE: 1980' FSL & 660' FWL, Sec. 2 AT TCP PROD. INTERVAL: Appx. same	12. COUNTY OR PARISH: 13. STATE San Juan New Mexico
AT TOTAL DEPTH: Appx. same	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	None Assigned
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	5643 CR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) SHOOT OR ACIDIZE DEC	CONOTE: Report of multiple completion or zell, change on Form JAN 06 1984 CON. DIV. CON. DIV. CON. DIV. CON. DIV. CON. DIV.
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinent	MIECHORAMY OFFICER, KIVE SUBSULTACE TOCATIONS AND
ARCO has plugged and abandoned the subject wel	w the BLM-MMS on January 11, 1983
Notice dated December 30, 1982, and approved b Injection interval 1551' - 1594' OA,	Gallup fm. Spotted cement plugs
	•
as per the attached plugging operations report	•
Completed P & A, 8-16-83.	
Final restoration will be commenced as soon as subsequent report will be filed when restorati	weather permits. An additional on has been completed.
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
13. Thereby certify that the foregoing is true and correct	
SIGNED Strhe Rose TITLE Dist. Prod. Su	pt. DATE November 30, 1983
S. C. Rose (This space for Federal or State office use)	

DATE ____

HSG #250, Horseshoe Gallup Field

P & A OPERATIONS:

MI RU. Released pkr & POH. TIH w/OE, spotted 15 sx cmt across the Galup perfs. PU 20 jts tbg & SDON.

FINAL REPORT - WELL P & A 8/16/83. Circ hole clean, perf'd 4 holes @ 1401' & spotted 30 sx plug. PU & squeezed 15 sx thru perfs. Perf'd 2 holes @ 146', pmpd 30 sx cmt leaving csg full of cmt. Installed dry-hole marker, RD & MO.