

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

SF-080212

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

MALCO COPPLE

9. WELL NO.

MALCO COPPLE # 6

10. FIELD AND POOL, OR WILDCAT

verde MALLUP

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

S5 30N 15W

12. COUNTY OR PARISH 13. STATE

SAN JUAN N.M.

OIL WELL  GAS WELL  OTHER

WATER DISPOSAL

2. NAME OF OPERATOR

Hebeo Oil Co.

3. ADDRESS OF OPERATOR

4381 BOY SCOUT LAKE EL PASO TX. 79922

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

SEC. 5 T30N R15W  
SAN JUAN COUNTY

14. PERMIT NO.

15. ELEVATIONS (Show whether OP, RT, OR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON\*

SHOOTING OR ACIDIZING

ABANDONMENT\*

REPAIR WELL

CHANGE PLANS

(Other) Conversion to water disposal

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

AUG 25 RAN PRESSURE TEST ON CASING.  
RAN 1000 lbs pressure ON TENTION PACKER in hole.  
Pressure dropped down to 650 lbs. AND held.  
Pressured up 3 TIMES AND HAD SAME RESULT:  
Pressure leak off due to packer, test showed casing  
integrity is okay. This sundry is subsequent report of water disposal conversion

18. I hereby certify that the foregoing is true and correct

SIGNED

W. H. Hand

TITLE

Vice Pres.

ACCEPTED FOR RECORD

(This space for Federal or State office use)

APPROVED BY

TITLE

AUG 31 1983

CONDITIONS OF APPROVAL, IF ANY:

FARMINGTON RESOURCE AREA

BY

Sm

\*See Instructions on Reverse Side