

**UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY**

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

<p><b>SUNDRY NOTICES AND REPORTS ON WELLS</b></p> <p>(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)</p>		<p>5. LEASE DESIGNATION AND SERIAL NO. <b>14-08-0001-8200</b></p> <p>6. IF INDIAN, ALLOTTEE OR TRIBE NAME <b>Navajo - Ute Mountain</b></p> <p>7. UNIT AGREEMENT NAME <b>Horseshoe Gallup Unit</b></p> <p>8. FARM OR LEASE NAME <b>Horseshoe Gallup</b></p> <p>9. WELL NO. <b>229</b></p> <p>10. FIELD AND POOL, OR WILDCAT <b>Horseshoe Gallup</b></p> <p>11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <b>Sec. 2-30N-16W</b></p>
<p>1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> <b>Injection</b></p> <p>2. NAME OF OPERATOR <b>Atlantic Richfield Company</b></p> <p>3. ADDRESS OF OPERATOR <b>1860 Lincoln Street, Suite 501, Denver, Colorado 80203</b></p> <p>4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface  <b>Unit B, 720' f/North &amp; 2040' f/East lines, Sec. 2</b></p>	<p>14. PERMIT NO.</p> <p>15. ELEVATIONS (Show whether DF, RT, GR, etc.) <b>5627'</b></p>	<p>12. COUNTY OR PARISH <b>San Juan</b></p> <p>13. STATE <b>New Mexico</b></p>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <u>Shut In</u>	

\*(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

This well was shut in 5-31-67 in order to evaluate effectiveness of injection on east side. U.S.G.S. approval was dated 5-24-67.

This well is in a large Unit which is now under waterflood operation. Future plans are to conduct waterflood and tertiary recovery studies. These studies may result in a revised waterflood plan or in a tertiary recovery program that may require the use of this well in order to recover the maximum amount of oil from this reservoir.

Two (2) copies sent to New Mexico Oil Conservation Commission

18. I hereby certify that the foregoing is true and correct

SIGNED W.A. Walther, Jr. /ps TITLE Dist. Prod. & Drlg. Supt. DATE 10/21/74  
W. A. Walther, Jr.  
 (This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
 CONDITIONS OF APPROVAL, IF ANY: