


(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Indian Agency Navajo

Allottee \_\_\_\_\_

Lease No. 14-20-603-2021

SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	<u>OCT 1</u>	<u>1958</u>
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING		
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	<u>U. S. GEOLOGICAL SURVEY</u>	<u>FARMINGTON, NEW MEXICO</u>
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIRING		
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT		
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY		
NOTICE OF INTENTION TO ABANDON WELL				

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 7, 19 58


Well No. Navajo D-1 is located 330 ft. from [N] line and 1650 ft. from [E] line of sec. 5  
NE 1/4, NE 1/4, Sec 5 30N 17W N.M.P.M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Undesignated San Juan New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the Ground Level above sea level is 1072.1 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The well was plugged w/20 sz. cement from 1260' - 1158'; 20 sz. cement 680' - 578'; 5 sz. from 75' - 50' and 5 sz. 25' to surface. An appropriate dry hole marker was established and the well abandoned.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company King Oil Company

Address Val R. Reese & Associates, Inc.

120 So. Commercial

Farmington, New Mexico

Original signed by T. A. Dugan

By \_\_\_\_\_

Title Consulting Engineer