

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL GAS
PRODUCTION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company El Paso Natural Gas Company				Address P.O. Box 990, Farmington, New Mexico			
Lease Sunray	Well No. 2-G	Unit Letter G	Section 21	Township 31N	Range 9W		
Date Work Performed 10-7-64	Pool Blanco			County San Juan			

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☐ Other (Explain):
☐ Plugging
 ☒ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Perforated tubing to eliminate loss of production due to bridge in open hole.
Shot 3 - 1/4" holes at 5205 feet. Good communication after perforating.



Witnessed by D. C. Adams	Position Production Engineer	Company El Paso Natural Gas Company
-----------------------------	---------------------------------	--

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA			
D F Elev.	T D 5745	P BTD 5745	Producing Interval 5113-5572
Completion Date 6-17-55			
Tubing Diameter 2-3/8"	Tubing Depth 5712	Oil String Diameter 7"	Oil String Depth 5067

Perforated Interval(s)

Open Hole Interval 5067-5745	Producing Formation(s) Mesa Verde
---------------------------------	--------------------------------------

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION		I hereby certify that the information given above is true and complete to the best of my knowledge.	
Approved by <i>Emory Cleveland</i>	Name <i>W. L. Williams</i>		
Title Supervisor Dist. # 3	Position		
Date 10-9-64	Company		