



STATE OF NEW MEXICO

ENERGY, MINERALS and NATURAL RESOURCES DIVISION
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE



BRUCE KING
GOVERNOR

ANITA LOCKWOOD
CABINET SECRETARY

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

August 31, 1993

Mr. Greg LeBlanc
Meridian Oil Inc.
PO Box 4289
Farmington NM 87499

RE: Seymour #7, A-23-31N-09W
Bradenhead Testing

Dear Mr. LeBlanc:

The enclosed copy of the 1993 Bradenhead Test on the referenced well indicates the bottom spool has not been dug out. Our records show the well has 7" casing at 5026' and a full string of 4-1/2" at 5920'. A review of past records shows the well was not dug out in 1990 and has probably never been properly tested. Please dig out, reschedule and retest the well prior to December 31, 1993.

Notify this office 24 hours prior to the test so that we may provide a witness.

Yours Truly,

Dianna K. Fairhurst

Dianna K. Fairhurst
Deputy Oil & Gas Inspector

xc: Bradenhead File
Well File
Susan Dolan - MOI



STATE OF NEW MEXICO
ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

BRADENHEAD TEST REPORT
(Submit 2 copies to above address)

Date of Test 8-25-93 Operator MOI
Lease Name SEYMOUR Well No. 7 Location: Unit A Section 23 Township 31N Range 09W
Pressure (Shut-in or Flowing) _____ Tubing 28 Intermediate N/A Casing 109 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 min.			Steady Flow	
10 min.			Surges	
15 min.			Down to Nothing	
20 min.			Nothing	
25 min.			Gas	
30 min.			Gas & Water	
			Water	

If Bradenhead flowed water, check description below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____

REMARKS:

DIARRA. THIS IS A GOOD CANDIDATE FOR A NRESE LOG. IN 63' THEY
SQUEEZED CEMENT THRU PERFS IN THE FRUITLAND TO STOP BY
FLOW. & IN 70' THEY WHIPSTICKED & DEVELOPED HOLES IN THE 7"

By Syphon A. Stamen Witness Ernie Busch

(Position)

FROM 830' TO 3060' APPROX. LATER ON THEY RAN 4 1/2"
TO T.D. WITH NO MONITORING SPOOL. (E)

RECEIVED

AUG 25 1993

OIL CON. DIV.

DIST. 3

OIL CONSERVATION DIVISION
1000 Rio Brazos Road
Albuquerque, New Mexico

BRADENHEAD TEST REPORT
(Submit 2 copies to above address)

Date of Test 12-12-90 Operator MERIDIAN OIL INC.

Lease Name SEYMOUR Well No. 7 Location U A Sec. 23 Twp. 31N Rge. 9W

Pressure (Shut-in or Flowing) Dwt Tubing > 1 Intermediate --- Casing 157 Bradenhead Open

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH.

TIME:	PRESSURES:	
	INTERMEDIATE	CASING
5 Min.		
10 Min.		
15 Min.		
20 Min.		
25 Min.		
30 Min.		

BRADENHEAD FLOWED:	INTERMEDIATE FLOWED:
Steady Flow	
Surges	
Down to Nothing	
Nothing <input checked="" type="checkbox"/>	
Gas	
Gas & Water	
Water	

If Bradenhead flowed water check description below:

Clear ---
Fresh ---
Salty ---
Sulfur ---
Block ---

Remarks: D.
Pump Jack
on location

RECEIVED

JAN 4 1991

OIL CON. DIV.
DIST. 3

By Stephen A. Starnes

LEASE OPERATOR

Position

Witness ---

DEC 26 1990