UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

5.	LEASE			
	SF	078508		

6.	IF INDIAN.	AL I	OTTER	OR	TRIBE	NAM

(Do not use this form for proposals to drill or to deepen or plug back to a different

16361	70h . U	30 10	3 331	0 10	such proposition
1.	oil well		gas well	X	other

2. NAME OF OPERATOR

Supron Energy Corporation

3. ADDRESS OF OPERATOR

AT TOTAL DEPTH:

- P.O. Box 808, Farmington, New Mexico 87401
- 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 AT SURFACE: 1605 Ft./S; 800 Ft./W line AT TOP PROD. INTERVAL: Same as above

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

Same as above


7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME Nordhaus 9. WELL NO. 2 10. FIELD OR WILDCAT NAME Blanco Mesaverde 11. SEC., T., R., M., OR BLK. AND SURVEY OR Sec. 11, T-31N, R-9W, N.M.P.M. 12. COUNTY OR PARISH 13. STATE New Mexico San Juan 14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD) 6494 R.K.B.

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Ran Plunger

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

- 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*
- Broached 2" tubing to seating nipple at 5591 ft.
- 2. Ran bumper spring and plunger.
- 3. Job completed 9/3/80.



DIST. 3

Subsurface Safety Valve: Manu. and Type _

Set @

18. I hereby certify that the foregoing is true and correct

5.

TITLE Production Supt. DATE _

September 9,

(This space for Federal or State office use)

APPROVED BY CONDITIONS OF APPROVAL, IF ANY: TITLE

DATE

SEP 15 1980

FARMINGTON DISTRICT

*See Instructions on Reverse Side