DEPUTY OU & GAS MODERATOR

DEC 22 1997

Meter Number: 75854
Location Name: FLORANCE D #2
Location: TN-30 RG-09
SC-23 UL-E
2 - Federal
NMOCD Zone: OUTSIDE
Hazard Ranking Score: 00

DECEIVED N APR 1 4 (397

RATIONALE FOR RISK-BASED CLOSURE OF PRODUCTION PITS LOCATED OUTSIDE OF THE VULNERABLE ZONE IN THE SAN JUAN BASIN

This production pit location was ranked according to the criteria in the New Mexico Oil Conservation Division's Unlined Surface Impoundment Closure Guidelines and received a ranking score of zero. The estimated depth to groundwater is greater than 100-feet beneath ground surface (bgs), the pit is not in a well head protection area, and there are no surface water bodies within 1,000 horizontal feet of the pit location.

The primary source, discharge to the pit has been removed. There has been no discharge to the pits for at least 4 years and the pits have been closed for at least one year.

Each pit was backfilled with clean soil and graded in a manner to divert precipitation away from the excavated area. Minimal infiltration of rainfall is expected. Any rainfall that does infiltrate the ground surface must migrate through clean backfill before reaching the residual hydrocarbons.

There is no source material at the ground surface, so direct contact of hydrocarbons with livestock and the populous is not likely.

In general, outside of the vulnerable area and alluvial valleys, bedrock material is generally encountered within 20 feet of the ground surface. Bedrock material in the San Juan Basin consists of interbedded sandstones, shales and clays. According to Freeze and Cherry, 1979, the hydraulic conductivity of the bedrock material are as follows:

Sandstone 10^{-9} to 10^{-13} cm/sec Shale 10^{-12} to 10^{-16} cm/sec Clay 10^{-12} to 10^{-15} cm/sec

Based on this information, the residual hydrocarbons should not migrate to groundwater.

Natural process (bioremediation) are degrading the residual hydrocarbon to carbon dioxide and water and will continue until the source is gone, therefore minimizing any impact to the environment.

Based on the above information, it is highly unlikely that any source material will impact groundwater or ever find an exposure pathway to affect human health and therefore El Paso Field Services Company (EPFS) requests closure of this pit location.



FIELD PIT SITE ASSESSMENT FORM


GENERAL	Meter: 75854 Location: Florance D #2 Operator #: 0203 Operator Name: Amoco P/L District: BloomField Coordinates: Letter: E Section 23 Township: 30 Range: 9 Or Latitude Longitude Pit Type: Dehydrator Location Drip: X Line Drip: Other: Site Assessment Date: 4.26.94 Area: 10 Run: 33
	NMOCD Zone: (From NMOCD Maps) Inside Outside Land Type: BLM (1) State (2) Fee (3) Indian
1	Depth to Groundwater Less Than 50 Feet (20 points) □ (1) 50 Ft to 99 Ft (10 points) □ (2) Greater Than 100 Ft (0 points) □ (3)
SITE ASSESSMENT	Wellhead Protection Area: Is it less than 1000 ft from wells, springs, or other sources of fresh water extraction?, or; Is it less than 200 ft from a private domestic water source? ☐ (1) YES (20 points) ☒ (2) NO (0 points)
	Horizontal Distance to Surface Water Body Less Than 200 Ft (20 points)
	(Surface Water Body: Perennial Rivers, Major Wash, Streams, Creeks, Irrigation Canals, Ditches, Lakes, Ponds) Distance to Nearest Ephemeral Stream (1) < 100'(Navajo Pits Only) (2) > 100' TOTAL HAZARD PANKING SCORE: POINTS
	TOTAL HAZARD MANMING SCORE.
REMARKS	Remarks: THERE PITS ON LOCATION. WILL CLOSE ONLY AND PIT IS DILY. LOCATION IS ON TOP OF A TRILL MESA. REDUNE AND TOPO CONFIRMED LOCATION
MA	TO BE OUTSIDE THE V.Z.
HE HE	(Push IN)

REMARKS

ORIGINAL	PIT	LOCA	TION
CANAGINATION		$\mu \nu \nu \kappa$	1 1 1 / I V

Original Pit : a) Degrees from North <u>so°</u> Footage from Wellhead <u>75′</u>

b) Length : ________ Width : ________ Depth : _________



R	en	ıar	ks	:

TOOK PICTURES AT 12:25 P.M.

END DUMP

Completed By:

Kaled Thompson

Signature

4.26.94

Date

GEL RAL	Meter: 75854 Location: Florance D # > Coordinates: Letter: E Section 23 Township: 30 Range: 9 Or Latitude Longitude Date Started: 5-18-94 Area: 10 Run: 33
FIELD OBSERVATIONS	Sample Number(s): \(\frac{\fr
CLOSURE	
REMARKS	Remarks: EPNG line Markers y' sandstone Pit had a lot of paratin Signature of Specialist: Vall Julian (SP3191) 04/07/94

	-



FIELD SERVICES LABORATORY ANALYTICAL REPORT PIT CLOSURE PROJECT - Soil

SAMPLE IDENTIFICATION

	Field ID	Lab 1D	
SAMPLE NUMBER:	10107	945223	
MTR CODE SITE NAME:	75854	N/A	
SAMPLE DATE TIME (Hrs):	5-18-94	1045	
SAMPLED BY:	N/A		
DATE OF TPH EXT. ANAL.:	5-19-94	5/19/94	
DATE OF BTEX EXT. ANAL.:	NIX	N/A	
TYPE DESCRIPTION:	٧6	Grey asurse sand	
		V	

REMARKS:	

RESULTS

PARAMETER	RESULT	UNITS	QUALIFIERS			
PANAMETEN	2001		DF	Q	M(g)	V(ml)
BENZENE		MG/KG				
TOLUENE		MG/KG				
ETHYL BENZENE		MG/KG				
TOTAL XYLENES		MG/KG				
TOTAL BTEX		MG/KG				
TPH (418.1)	32,100	MG/KG			0,20	28
HEADSPACE PID	157	PPM	<u> </u>		<u> </u>	
PERCENT SOLIDS	83.5	%			<u></u>	

I EKCENT SOZES	<u> </u>		
	- TPH is by EPA Method	418.1 and BTEX is by EPA Me	thod 8020 —
The Surrogate Recovery was at	ALA	% for this sample	All QA/QC was acceptable.
Narrative:			

DF = Dilution Factor Used

Date: <u>4/15/44</u>

	ļ

Test Method for
#
Oil and Grease and Petroleum Hydrocarbons *
in Water and Soil
*

44/05/19 15:47


- , *

Sample identification 145223

Thibial mass of sapple, g 1,200

Volume of sample after extraction, al 15.000

Fetroleum hydronarions, ppm Toic4.458 Nat absorbance of hydrocarbons (2770 cm-1) T71



	• · · · · · · · · · · · · · · · · · · ·	