
F

Casing S.		Cu. ft.	Elev. <u>7355 GL</u> Spd. @W	Cu. ft. _Sx. Pr	Comp	\	" w	Cu. ft. Sx. T.	P	в @	
sg.Perf.				Prod. Stim.						T Gas	
P,	BO/D MCF/D After	Hrs. SICP	PSI After Day								N S
TOPS		NITD X Well Log		TEST DATA							
€io Alamo		C-103	Plat X		Schd.	PC	Q	PW	PD	D	Ref.No
ristland		C-104	Electric Log								1
Fruitland			C-122								
Pictured Cliffs		Ditr	Dfa	•							1
Chacra		Dair	Dac								
Cliff House											
Menefee		7							Ī		
Point Lookout									Ì		
Mancos		7									
Gallup									Ī		
Greenhorn								1			
Dakota		7						1			
Entrada											
_			Acres	160							1





United States Department of the Interior

BUREAU OF LAND MANAGEMENT Caller Service 4104 Farmington, New Mexico 87499

NOV 25 1985

CERTIFIED--RETURN RECEIPT REQUESTED

Frontier Energy Corporation 1360 Post Oak Boulevard, Suite 790 Houston, TX 77056

Gentlemen:

Enclosed is your Application for Permit to Drill (APD) well No. 17-D Arboles, SW/4SW/4 Sec. 17, T. 32 N., R. 4 W., Rio Arriba County, New Mexico, lease NM-28277. As discussed with Mr. Robert Davant of your Company on November 19, 1985, the subject APD is rescinded and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 15 days, we will presume that no construction occurred. Later discovery that construction activities have in fact occurred, will result in an assessment.

Sincerely,

Mat Millenbach Area Manager

Enclosure

cc:

Nov 2 6 1985
OIL COM. BIV.)
DIST. 3

ABANDONEL LOCATION