

D-14-32N-4w

Current
Status

JEROME P. McHUGH/NASSAU RESOURCES, INC.
P O BOX 809
FARMINGTON, N.M. 87499-0809
505 326-7793

MORNING REPORT

WELL: Carracas Mesa 14 #1

DATE: 10/25/88

DEPTH @ 6:00 A.M.: 5838'

OPERATION @ 6:00 A.M: REAMING
WORKING ON KEYSEATS
DAYS SINCE SPUD: 39

FOOTAGE DRILLED LAST 24 HRS: 0
OPERATIONS LAST 24 HRS:

HRS. DRILLING
HRS. LOGGING
HRS. TESTING
HRS. REPAIR
HRS. CASING

HRS. TRIPPING
HRS. REAMING 10-1/2
HRS. WRKING.TIGHT SPTS. 7-1/2
HRS. L.D. REAMERS 2
HRS. PU TAPERED REAMERS 4

MUD PROPERTIES:

WEIGHT	10.3	VIS	60	WATER LOSS	6
PH	9	SOLIDS	21	OIL %	
PV	20	YP	8	LCM	3%

NO MUD LOSS OR GAIN.

CUM MUD COST \$56,980

SURVEYS:

BIT SUMMARY:

SIZE	BIT NO. 11
MAKE	8-3/4"
TYPE	SMITH
DEPTH IN	F2
DEPTH OUT	5724'
FTG. DRLD.	5838'
ROTATING HRS.	114'
NOZZLE SIZE	21-1/2
CONDITION	12-12-12
FT./HR.	

W.O.B. 0#

RPM

H.L. 30,000#

REMARKS: REAMING 395-1178'.

RECEIVED
OCT 26 1988
OIL CON. DIV
DIST. 3