asing S asg.Perf.	1000/N; 620, w	Cu. ft.	elev	w	Cu. ft. Sx. Pr. Prod. Stim.			v	Cu. ft. Sx. T	PI	@	Ţ Gas
P	BO/D	Hrs SICP	PSI	After							_	N S
TOPS		Hrs.         SICPPSI AfterDays GOR_           NITD         X           Well Log			TEST DATA							
Ojo Alamo		C-103		Plat >	ζ	Schd.	PC	Q	PW	PD	D	Ref.No.
Kirtland		C-104		Electric Log						<u> </u>		
Fruitland		I		C-122								
Pictured Cliffs		Ditr		Dfa						<u> </u>		
Chacra	-	Datr		Dac						<u> </u>	<u> </u>	
Cliff House											<b></b>	
Menefee											<u> </u>	
Point Lookout										ļ	<u> </u>	<b>_</b>
Mancos											<u> </u>	
Gallup										ļ	<del> </del>	
Greenhorn						<u> </u>	ļ				<u> </u>	
Dakota					2506	<u> </u>			<b></b>	ļ	<b>_</b>	
Entrado					NSL-2596 N/320			ļ <u> </u>	<b></b>		ļ	
					Acres	l			<u> </u>			

Carracas Unit 15A #1 A-15-32N-5W

NASSAU RESOURCES, INC.

MAR, 27 1990

CERTIFIED-RETURN RECEIPT REQUESTED P-140-441-586

Nassau Resources, Incorporated P. O. Box 809 Farmington, NM 87499

Gentlemen:

Enclosed is your Application for Permit to Drill (APD) well No. 1 Carracas Unit 15A, NE/4NE/4 sec. 15, T. 32 N., R. 5 W., Rio Arriba County, New Mexico, lease NM-30351. As discussed with James Hazen of your company on January 20, 1990, the subject APD is rescinded and returned.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, will result in strict enforcement of 43 CFR 3163.1.

Sincerely,

Ken Townsend

FOR Ron Fellows
Area Manager

Enclosure

cc: New Mexico Oil Conservation Divison, 310 Old Santa Fe Trail, Room 206, Santa Fe, NM 87503

## ABANDONED LOCATION

## ABANDONED LOCATION