

(SUBMIT IN TRIPLICATE)

Indian Agency Navajo

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee

Lease No. 14-20-604-1951

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

RECEIVED
JUL 24 1958
U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

Well No. Ute No. 2 is located 2140 ft. from S line and 735 ft. from W line of sec. 34

SW 1/4 Sec. 34 1N 10W 101PM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Verde Gallup San Juan
(Field) (County or Subdivision)
(State or Territory) New Mexico

The elevation of the derrick floor above sea level is 5375 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

7-20-58. Total depth - 1328.41 feet.

Ran 40 joints 7", 20#, 4-55 casing (1304.78') at 1310' with 100 sacks regular cement, 46 gal. Held 1000# for 30 minutes. Circulated top of cement at 770#.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Banner Drilling Company

Address Box 1571

Farmington

New Mexico

By

Ben Banner

Title

Co-Owner

