

STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

TONEY ANAYA

December 20, 1985

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87410 (505) 334-6178

Mr. Rex Hitchcock Arco Oil & Gas Co. 1816 E. Mojave Farmington, NM 87401

Re: Horseshoe Gallup Unit #253 N-04-30N-16W
Horseshoe Gallup Unit #126 D-05-30N-16W
Horseshoe Gallup Unit #134 H-05-30N-16W
Horseshoe Gallup Unit #267 F-09-30N-16W
Horseshoe Gallup Unit #180 D-34-31N-16W
Horseshoe Gallup Unit #192 F-34-31N-16W
Horseshoe Gallup Unit #201 L-34-31N-16W
Horseshoe Gallup Unit #69 C-14-31N-17W

Dear Mr. Hitchcock:

Annual mechanical integrity tests on the referenced water injection wells indicate casing or packer leaks. In order to insure the protection of hydrocarbon and fresh water zones, you are hereby directed to initiate remedial action within 60 days.

If you have any questions, please contact this office.

Yours truly,

Carolyn J. Taplin

Field Representative

CJT/di

xc: Well Files

Operator File

UIC File

Prentiss Childs