

(SUBMIT IN TRIPLICATE)

Indian Agency

**NAI-50**  
**NAI-**

UNITED STATES

DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

Allottee

Lease No. **14-20-604-1981**

	<b>X</b>		

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**November 30**

19 **58**

Well No. **5** is located **2310** ft. from **[N]** line and **1650** ft. from **[W]** line of sec. **34**

**82-NW-34**

(1/4 Sec. and Sec. No.)

**3 IN**

(Twp.)

**16W**

(Range)

**NMPM**

(Meridian)

**Horse Shoe G. llup Ext.**

(Field)

**San Juan**

(County or Subdivision)

**New Mexico**

(State or Territory)

The elevation of the derrick floor above sea level is **5390** ft.

### DETAILS OF WORK


(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

**11/9/58 Total Depth 1420:**

**Ran 43 Jts - 15# - 5-1/2' CSG, 1361' with 100 Sacks Reg. Cement,**

**Held 1000# for 30 minutes.**

**Circulated Top Cement 700 Ft.**



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Banner Drilling Company**

Address **P.O. Box 1571**

**Farmington**

**New Mexico**

By **Bew Banner**

Title **Co-Owner**