

(SUBMIT IN TRIPLICATE)

Indian Agency **Navajo-Ute**

<b>X</b>		

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Allottee \_\_\_\_\_  
Lease No. **14-20-604-1951**

**SUNDRY NOTICES AND REPORTS ON WELLS**

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<b>X</b>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**March 6**, 19**59**

**Horseshoe Ute**

Well No. **5** is located **1980** ft. from **[N]** line and **4470** ft. from **[E]** line of sec. **33**

**SW NW/4 Sec. 33**

**31N**

**15W**

**NMPM**

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

**Horseshoe Gallup**

**San Juan**

**New Mexico**

(Field)

(County or Subdivision)

(State or Territory)


The elevation of the derrick floor above sea level is **5401** ft.

**DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

**Spud Date 3-4-59. 3-4-59 Total Depth 110'.**

**Ran 3 joints, 8-5/8", 32.00#, J-55 Csg. ( 93.22' ) set at 100.22' with 100 sacks regular cement, 2% CaCl<sub>2</sub> circulated to surface. Held 500#/ 30 Minutes.**



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **El Paso Natural Gas Products Company**

Address **Post Office Box 1565**

**Farmington, New Mexico**

**ORIGINAL SIGNED BY: JOSEPH E. KREGER**

By \_\_\_\_\_

Title **Petroleum Engineer**