

(SUBMIT IN TRIPLICATE)

Budget Bureau 170. 22
Approval expires 12-31-60.

Indian Agency **NAV-Ute**

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee **14-20-604-1951**
Lease No. _____

X				

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

RECEIVED

DEC 15 1958

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

November 28

19**58**

Well No. **6** is located **990** ft. from **N** line and **1905** ft. from **E** line of sec. **34**
N.W. 34 **3112** **16 W** **NMPM**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Horse Shoe Gallup Ext **San Juan** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **5530** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud Date **11-16-58.** **11/16/58 T.D. 124 Ft.**

Ran 4 Jts - **8-5/8 244 J 55 CSG (115 ft.)**

Set at 114 Ft. with 100 Sacks Reg. Cement,
circulated to surface, Held 3004, 30 minutes.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Banner Drilling Co.**
Address **P. O. Box 1571**
Farmington, New Mexico

By **Bew Banner**
Title **Co-Owner**

RECEIVED

SEP 11 1958

WASHINGTON NEW MEXICO
U.S. AIR FORCE

100-100000-100000