

| | | | |
|--|---|--|--|
| | | | |
| | | | |
| | | | |
| | X | | |

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency

Ute Mountain Tribal

Allottee

Lease No. 14-20-604-125

SUNDRY NOTICES AND REPORTS ON WELLS

| | |
|---|--|
| NOTICE OF INTENTION TO DRILL | SUBSEQUENT REPORT OF WATER SHUT-OFF |
| NOTICE OF INTENTION TO CHANGE PLANS | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF | SUBSEQUENT REPORT OF ALTERING CASING |
| NOTICE OF INTENTION TO REDRILL OR REPAIR WELL | SUBSEQUENT REPORT OF REDRILLING OR REPAIR |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE | SUBSEQUENT REPORT OF ABANDONMENT |
| NOTICE OF INTENTION TO PULL OR ALTER CASING | SUPPLEMENTARY WELL HISTORY |
| NOTICE OF INTENTION TO ABANDON WELL | |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Ute Mountain Tribal "E"

Farmington, New Mexico March 17, 1960

Well No. 4 is located 990 ft. from NS line and 1850 ft. from EW line of sec. 26

SW/4 of Section 26 T-31-N R-15-W N.M.P.M.
(¼ Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Verde Gallup San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5461 ft. (GL)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Ute Mountain Tribal "E" Well No. 4 was plugged and abandoned as follows on March 10, 1960, as a result of not obtaining oil or gas in commercial quantities:

1. Spotted 15 sacks cement plug in 5-1/2" casing 3829-3954.
2. Filled hole with fluid.
3. Spotted 50 sacks of cement down 5-1/2" - 8-5/8" annulus to anchor pipe.
4. Removed wellhead and surface equipment.
5. Spotted 5 sacks of cement for surface plug (0-40') and erect dry hole marker.
6. Plug and abandonment operations by above procedure to permit possible re-entry for future secondary purposes.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Pan American Petroleum Corporation

Address Box 487

ORIGINAL SIGNED BY
R. M. Bauer, Jr.

Farmington, New Mexico

By _____

Attn: L. O. Spiser, Jr.

Title Area Engineer

