


STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSION

DISTRICT NO. 3
Phone 99 P. O. Box 697
AZTEC, NEW MEXICO

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____
Lease No. **NE 0606**
Unit _____



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Atlantic **June 26**, 19**51**
Well No. **1-7** is located **1650** ft. from **(N)** line and **990** ft. from **(E)** line of sec. **27**
NE 1/4 Sec. 27 **T-31-N** **R-10-W** **E. E. P. E.**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Blanco **San Juan** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **6250** ft. **G. L. (alt.)**

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)


Well was drilled to T.D. of 5620' where 7" casing was set. Rotary then drilled with gas to T.D. of 5473' for "one foot" completion. Well was shot with 1960 lbs. of NO. 4710' to 5473' open hole shot. The well was open nine hours and cleaned itself out, well tested open three 7 1/2 hours, 4070 MB. Run 153 joints of 2" 4-70' 8-40 tubing landed at 4637', tree set, and well shut in 6/23/51.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Dalhi Oil Company**
Address **Box 1175**
Farmington, New Mexico
By **J. B. Howell**
Title **Superintendent**

Land Office _____
 Lease No. _____
 Unit _____

**DEPARTMENT OF THE INTERIOR
 GEOLOGICAL SURVEY
 UNITED STATES
 (SUBMIT IN TRIPLICATE)**



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO ABANDON WELL	
NOTICE OF INTENTION TO PULL OR ALTER CASING	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	
NOTICE OF INTENTION TO DRILL	
SUPPLEMENTARY WELL HISTORY	
SUBSEQUENT REPORT OF ABANDONMENT	
SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
SUBSEQUENT REPORT OF ALTERING CASING	
SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
SUBSEQUENT REPORT OF WATER SHUT-OFF	

(Indicate above by checkmark the nature of report, notice, or other data)

The elevation of the derrick floor above sea level is _____ ft.

_____ (County or subdivision) _____ (State or Territory)

_____ (Twp) _____ (Range and Sec No.)

_____ is located _____ ft. from _____ line and _____ ft. from _____ line of sec. _____

DETAILS OF WORK

(State nature of and expected depths to objective sands; show sizes, weights, and lengths of proposed casing; indicate casing running depth, etc. with line points, and all other important proposed work)

[Faint, illegible handwritten text in the details of work section]

I understand that this plan of work must be approved by the Geological Survey before it can be carried out.

Company _____
 Address _____

 Title _____
 By _____