

Ute Mt. Tribal 2-29 #6


(SUBMIT IN TRIPLICATE)

Indian Agency Ute Mt.

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. 14-20-601-122



Sec 29 SUNDRY NOTICES AND REPORTS ON WELLS

| | |
|---|--|
| NOTICE OF INTENTION TO DRILL | SUBSEQUENT REPORT OF WATER SHUT-OFF |
| NOTICE OF INTENTION TO CHANGE PLANS | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF | SUBSEQUENT REPORT OF ALTERING CASING |
| NOTICE OF INTENTION TO REDRILL OR REPAIR WELL | SUBSEQUENT REPORT OF REDRILLING OR REPAIR |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE | SUBSEQUENT REPORT OF ABANDONMENT |
| NOTICE OF INTENTION TO PULL OR ALTER CASING | SUPPLEMENTARY WELL HISTORY |
| NOTICE OF INTENTION TO ABANDON WELL | |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Oct 1, 1959

Ute Mt. Tribal 2-29
Well No. 6 is located 1650 ft. from N line and 660 ft. from E line of sec. 29

SW/4, SW/4 Sec 29 31N 14W R14PM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Verde Calling San Juan County New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5526 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

The well was spudded 3:00PM 9-25-59. 2-5/8" casing was set at 11h and cemented with 100w neat cement. Cement was circulated to surface. After WOC 24 hrs., the pipe was tested okay with 1000psi for 30 min. A 7-7/8" hole is presently being drilled ahead at 1900'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Standard Oil Company of Texas

Address Box 1581

Farmington, New Mex.

By C. L. Hartney

Title Field Foreman

