

District I

P.O. Box 100, Hobbs, NM

District II

P.O. Box 100, Hobbs, NM

District III

1000 Rio Brazos Rd., Hobbs, NM 88241

State of New Mexico

Energy, Minerals and Natural Resources Department

SUBMIT 1 COPY TO

APPROPRIATE

DISTRICT OFFICE

AND 1 COPY TO

SANTA FE OFFICE

DEPUTY INSPECTOR

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

PIT REMEDIATION AND CLOSURE REPORT

Operator: CHATEAU OIL AND GAS

Telephone: 505 632-8056

Address: 5802 US HIGHWAY 64, FARMINGTON, NM 87401

Facility Or: PAYNE 1
Well Name

Location: Unit or Qtr/Qtr Sec K Sec 35 T 31N R 13W County SAN JUAN

Pit Type: Separator ☒ Dehydrator ☒ Other ☐

Land Type: BLM ☒, State ☐, Fee ☐, Other ☐

Pit Location: Pit dimensions: length 10', width 10', depth 3'
(Attach diagram)

Reference: wellhead ☒, other ☐

Footage from reference: 120' West

Direction from reference: _____ Degrees _____ East North _____
of
_____ West South _____

Depth To Ground Water:

(Vertical distance from
contaminants to seasonal
high water elevation of
ground water)

Less than 50 feet (20 points)

50 feet to 99 feet (10 points)

Greater than 100 feet (0 Points) 0

Wellhead Protection Area:

(Less than 200 feet from a private
domestic water source, or; less than
1000 feet from all other water sources)

Yes (20 points)

No (0 points) 0

Distance To Surface Water:

(Horizontal distance to perennial
lakes, ponds, rivers, streams, creeks,
irrigation canals and ditches)

Less than 200 feet (20 points)

200 feet to 1000 feet (10 points)

Greater than 1000 feet (0 points) 0

RANKING SCORE (TOTAL POINTS): 0

PRINTED NAME SHAWN ADAMS
AND TITLE ENR. CONSULTANT


1-20-97

CHATEAU OIL

PAYNE #1

UNIT K SEC 35 T-31-N R-13-W

- #1 BOTTOM @ 6' 4.0 P.P.M.
- #2 E. BANK @ 6' 3.4 P.P.M.
- #3 S. BANK @ 6' 0.9 P.P.M.
- #4 W. BANK @ 6' 2.5 P.P.M.
- #5 N. BANK @ 6' 5.0 P.P.M.



CHAIN OF CUSTODY RECORD

B 101i

Date:

Page 1 of 1

612 E. Murray Dr. • P. O. Box 2606 • Farmington NM 87499
(505) 327-1072 • FAX: (505) 327-1496

[illegible]

Distribution:	White - On Site	Yellow - LAB	Pink - Sampler	Goldenrod - Client
---------------	-----------------	--------------	----------------	--------------------

OFF: (505) 325-5667



LAB: (505) 325-1556

ANALYTICAL REPORT

Attn: **Shawn Adams**
Company: **Contract Environmental Services, Inc.**
Address: **P.O. Box 505**
City, State: **Kirtland, NM 87417**

Date: **22-Jan-97**
COC No.: **B1011**
Sample No.: **13499**
Job No.: **2-1000**

Project Name: **Chateau Oil & Gas - Payne #1**
Project Location: **Pit Bottom @ 6'**
Sampled by: **CM** Date: **20-Jan-97** Time: **14:45**
Analyzed by: **HR** Date: **22-Jan-97**
Sample Matrix: **Soil**

Laboratory Analysis

Parameter	Result	Detection Limit	Unit of Measure	Method
Total Petroleum Hydrocarbons, TPH	< 25	25	mg/kg	EPA Method 418.1


Quality Assurance Report

Laboratory Fortified Blank/Spike Soil

Laboratory Identification	Analyzed Value	Acceptable Range	Unit of Measure
Laboratory Fortified Blank Soil - QCBS2	< 25	< 25	mg/kg
Laboratory Fortified Spike Soil - QCSS1	873	828 - 1024	mg/kg

Duplication

Laboratory Identification	(% RSD)	Limit (% RSD)
13449-B1011	< D.L.	15.0

Approved by: 
Date: **1/23/97**