

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency _____

Ute - Navajo

Allottee _____

Lease No. **14-20-604-1951**

SUNDRY NOTICES AND REPORTS ON WELLS **RECEIVED**

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____
NOTICE OF INTENTION TO ABANDON WELL _____	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

10-2-59

19

Well No. **5** is located **1670** ft. from **N** line and **330** ft. from **E** line of sec. **27**
(1/4 Sec. and Sec. No.)
Horseshoe Gulch (Field)
San Juan (Twp.) **16W** (Range) **10N** (Meridian)
New Mexico (State or Territory)


The elevation of the derrick floor above sea level is **9629** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

10-1-59

P.B. 1951, Set 54", 14-5, J-55, @ 1575, Cemented with 185 lbs. 25 gal, 1/2 of 15 floccul.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Petro Atlas Inc.**

Address **P.O. Box 1956**
Farmington, New Mexico

By **[Signature]**
Title **Supt.**