

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency _____
Ute Mountain Tribal
Allottee _____
Lease No. 14-20-604-88

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	<u>MAR 8 1961</u>
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASINGS	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Ute Mountain Tribal "C"

Farmington, New Mexico - March 6, 1961

Well No. 1 is located 2260 ft. from N line and 550 ft. from W line of sec. 27

SW 1/4 of Section 27 T-31-N R-15-W N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Verde Gallup San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5666 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging points, and all other important proposed work)

- Ute Mountain Tribal "C" Well No. 1 was plugged and abandoned as follows on February 27, 1961 as a result of well ceasing to produce oil in commercial quantities:
1. Moved in pulling unit and pulled rods and tubing.
 2. Ran Bowen releasing casing spear and Bowen jar and recovered 4-1/2" liner.
 3. Spotted 25 sacks cement plug down 5-1/2" casing and tagged top plug at 2336'.
 4. Filled hole with fluid.
 5. Pumped 25 sacks cement plug down 5-1/2" - 8-5/8" casing annulus.
 6. Removed wellhead and surface equipment.
 7. Spotted 5 sacks cement for surface plug (0-40) and erected abandonment marker.
 8. Above procedure to permit possible re-entry for future secondary recovery purposes.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company PAN AMERICAN PETROLEUM CORPORATION

Address P. O. Box 480

Farmington, New Mexico

Attn: L. O. Speer, Jr.

ORIGINAL SIGNED BY
R. M. Bauer, Jr.

By _____

Title Senior Petroleum Engineer