

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. 14-20-604-1939
2. NAME OF OPERATOR Benson-Montin-Greer Drilling Corp.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Ute Mountain Tribal
3. ADDRESS OF OPERATOR 221 Petroleum Center Building, Farmington, NM 87401		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FNL 660' FEL / Sec. 29, T31N, R14W		8. FARM OR LEASE NAME Ute Mountain Tribal 1939
14. PERMIT NO.	15. ELEVATIONS (Show whether OF, BY, OR, etc.) 5601' GR	9. WELL NO. #4
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data		10. FIELD AND POOL, OR WILDCAT Verde Gallup
17. DESCRIBE PROPOSED OPERATIONS (Clearly state all pertinent details, and give pertinent directional data for all markers and points pertinent to this work.)		11. SEC., T., R., M., OR B.L. AND SURVEY OR AREA Sec. 29, T31N, R14W
		12. COUNTY OR PARISH San Juan
		13. STATE New Mexico

RECEIVED
JUL 9 1991
OIL CON. DIV.

SUBSEQUENT REPORT OF:

TEST SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRAC TREAT	MULTIPLE COMPLETE	FRAC TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL (Other)	CHANGE PLANS	(Other)	

(NOTE: Report results of multiple completions or Completion or Recompletion Report and Log form.)

App. Exam.	
Mining Geo.	
Realty	
Pet. Eng.	
Env. Scientist	
Geol.	
Geophys.	
Hydro.	
Soil	
Water Resources	
Wildlife	
Other	

11/09/85 thru 11/22/85

Shot off 4" liner at approximately 3750' and pulled.

Cement plug #1 - Cement 5-1/2" 4024' to 3750' with 40 cubic feet cement slurry.

Shot off 5-1/2" casing at approximately 1563' and pulled.

Cement plug #2 - Cement plug on top of 5-1/2" casing with 60 cubic feet cement slurry from 1563' to 1460'. Ran tubing to top of cement, found top of cement plug at 1460'.

Cement plug #3 - Cement plug from 160' with 60 cubic feet. RIH with wireline found top of cement plug at 130'.

Cement plug #4 - Ran 2-3/8" tubing to 130'. Cemented with 46 cubic feet cement slurry. Cement to surface.

Erected dry hole marker and cleaned location.

RECEIVED
Bureau of Land Management
DEC 20 1985
Durango, Colorado

18 I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Vice President DATE _____

(This space for)

APPROVED BY Sally Wisely TITLE AREA MANAGER DATE JUL 18 1991

CONDITIONS OF APPROVAL, IF ANY:

Nmced
See Instructions on Reverse

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully in the United States any false, fictitious or fraudulent statements or representations a

ABANDONMENT OF THE WELLBORE AND SURFACE RESTORATION ARE COMPLETE. THE OPERATOR'S LIABILITY FOR THE WELL IS HEREBY RELEASED.