Form	9-8818	١
(Fob	1051)	

and the first of t		
7		
ם		
		i

(SUBMIT IN TRIPLICATE)

UNITED STATES **DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY**

E A	Sudget Bureau No. 42-R358.4. pproval expires 12-31-60.
Land Offic	Santa Fe
Lease No.	078097
** **	Heaton

SUNDRY NOTICES AND REPORTS ON WELLS			
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF		
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING		
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING.		
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR		
OTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT		
OTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY		
NOTICE OF INTENTION TO ABANDON WELL	Water Fracture		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

					April 23,		19_56
Well	No. 4	is located 1650	ft. from N	line and 1042	ft. from E	line of sec	2 9
HE	Section 29	3111	LIE	KAN	(••)	100	"
	(¼ Sec. and Sec. No.)	(Twp.)	(Range)	(Meri	idian)		11
Rla	BOCO		San	Amn	New M	xico ~	
	(Field)		(County or Subdivi	sion)	(State or 7	erritors)	- 13
The	elevation of the	derrick floor above	e sea level is	5982 ft.		# OIL	м. /
			DETAILS OF	F WORK		1 500	and the second
(State	names of and expected	depths to objective sands	s; show sizes, weigh s, and all other imp	ts,'and lengths of prop ortant proposed work	posed casings; indi	cate mudding	mont-

April 15, 1956 Pingback depth 4890'. Water fractured Lower Point Lookout perf. intervals 4842-4870 with 78,065 gal one water and 100,000# sand. Brenkdown pressure 1100%, maximum pressure 1700%, average treating pressure 1600%. Injection rate 55.5 bbls./min. Flush 12,898 gallons.

April 16, 1956 Bemp. F.B. Depth 4837'. Water fractured Upper Point Lookout perf. intervals 4300-4320 with 54,185 gallons water and 60,000% sand. Breakdown pressure 1700f, maximum pressure 2600f, average treating pressure 2450f. Injection rate 44.5 bbls./win. Flush 8610 gal ons.

I understan	nd that this plan of work must receive approval in writing	by the Geological Survey before operations may be commenced.
Company _	El Paso Mutaral Gos Company	
Address	Box 997	
	Formiogton, New Mexico	- mill Millach
		Title Petroleum Engineer
	* 1, m., 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1,	4 1010