

X		

(SUBMIT IN TRIPLICATE)

Indian Agency Ute

Contract No. 14-20-604-124

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Co. Lease No. 234674

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____	X
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____	
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____	
NOTICE OF INTENTION TO ABANDON WELL _____		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Ute Tribe "B" Lse.

Farmington, New Mexico Dec. 8, 1958

Well No. 2 is located 660 ft. from N line and 1980 ft. from E line of sec. 25

NE/4 of NW/4 25 31-N 15-W
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Verde Gallup San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5479 ft. Or.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

11/28/58: Spudded 12-1/4" hole at 3:00 A.M., 11/28/58.

11/27/58: Set 8-5/8" Casing at 131' w/125 sacks 2% calcium chloride cement. P.O.B. at 9:15 P.M., 11/27/58.

11/30/58: Tested casing w/750# CWP for 30 minutes - O.K. Drilled plug (40' of hard cement) at 10:00 P.M., 11/30/58.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Humble Oil & Refining Company

Address Box 1268

Farmington

New Mexico

By J. C. Wisley

Title Agent